FINAL REPORT FOR REMEDIATION OF LOCATIONS IN GRANITE CITY, MADISON, AND VENICE, ILLINOIS ASSOCIATED WITH NL INDUSTRIES/TARACORP SUPERFUND SITE

PRE-PLACED CONTRACT NO. DACA45-96-D-0014 DELIVERY ORDER NO. 0004

Submitted by:

OHM Remediation Services Corp. Midwest Region

Prepared by:

Tom Warren Project Manager

February 15, 1999 Project 19321

This information is the exclusive property of the party to whom it is addressed. OHM Remediation Services Corp. assumes no responsibility or liability for the reliance hereon or use hereof by anyone other than the party to whom it is addressed. ©1999 OHM Remediation Services Corp.



TABLE OF CONTENTS

- 1.0 INTRODUCTION
 - 1.1 SITE HISTORY
 - 1.2 DOCUMENT ORGANIZATION
- 2.0 SCOPE OF WORK
 - 2.1 PREPARATION OF SITE-SPECIFIC PLANS
 - 2.2 SITE ADMINISTRATION/LOGISTICAL SUPPORT
 - 2.3 MOBILIZATION/DEMOBILIZATION
 - 2.4 SITE PREPARATION AND TEARDOWN
 - 2.5 OPERATIONAL SCOPE OF WORK PERFORMED
 - 2.6 SAMPLING AND ANALYSIS
 - 2.7 TRANSPORTATION AND DISPOSAL
- 3.0 TECHNICAL APPROACH
 - 3.1 PRE-CONSTRUCTION ACTIVITIES
 - 3.2 SAMPLING AND ANALYSIS
 - 3.3 CHEMICAL DATA ACQUISITION PLAN AMENDMENTS/ADJUSTMENTS
 - 3.4 TRANSPORTATION AND DISPOSAL
- 4.0 HEALTH AND SAFETY SUMMARY
 - 4.1 PROJECT SUMMARY AND CONCLUSIONS
 - 4.2 SITE SAFETY AND HEALTH PLAN EVALUATION
 - 4.3 SITE SAFETY
 - 4.4 EXPOSURE MONITORING
- 5.0 QUANTITY SUMMARY TABLE
- 6.0 VERIFICATION ANALYTICAL SUMMARY TABLE
 - 6.1 STACK EMISSION SITES
- 7.0 PHOTO REPRESENTATION

APPENDIX A - FLOW CHARTS
APPENDIX B - REMEDIAL LOCATION WORK DESCRIPTIONS

1.0 INTRODUCTION

The United States Army Corps of Engineers (USACE) tasked OHM Remediation Services Corp. (OHM), a wholly owned subsidiary of OHM Corporation, under the Pre-Placed Contract No. DACA45-96-D-0014, Delivery Order (DO) No. 0004, to perform remediation of Stack Emission sites at various locations associated with the NL Industries/Taracorp Superfund Site (NL Site) in Granite City, Madison, and Venice, Illinois.

1.1 SITE HISTORY

The NL Site includes the NL Industries/Taracorp Plant, a former secondary lead smelting operation located at 16th and Cleveland Boulevard in Granite City, Illinois. Prior to 1903, the plant included various smelting related equipment and processes. From 1903 to 1983, secondary lead smelting occurred on site. These activities were discontinued during 1983 and the equipment was dismantled.

In July 1981, St. Louis Lead Recyclers, Inc. (SLLR) began using equipment on adjacent property owned by Trust 454 to separate components of the Taracorp waste pile. The objective was to recycle lead bearing materials to the furnaces at Taracorp and send hard rubber off site for recycling. SLLR continued operations until March 1983 when it shut down its equipment. Residuals from the operation remain on Trust 454 property as does some equipment.

A State Implementation Plan for Granite City, Illinois was published in September 1983 by the Illinois Environmental Protection Agency (IEPA). The IEPA's report indicated the lead non-attainment problem for air emissions in Granite City, Illinois, were in large part due to emissions associated with the operation of the secondary lead smelter operation by Taracorp and lead reclamation activities conducted by SLLR. The IEPA procured Administrative Orders by Consent with Taracorp, SLLR, Stackorp, Inc., Tri-City Truck Plaza, Inc., and Trust 454 during March 1984. The orders required the implementation of remedial activities relative to air quality.

NL Industries, as former owner of the location, voluntarily entered into an Agreement and Administrative Order by Consent with United States Environmental Protection Agency (USEPA) and IEPA in May 1985 to implement a Remedial Investigation/Feasibility Study (RI/FS) for the location and other potentially affected areas. Taracorp was not a party to the agreement due to the fact it filed for bankruptcy. The USEPA determined the location was a Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA) facility and it was placed on the National Priorities List on June 19, 1986.

1.2 DOCUMENT ORGANIZATION

This final project report is intended to provide a detailed description of the tasks involved in performing the work. Section 2.0 describes the scope of work involved in the preparation of the site-specific plans, performance of site administration/logistical support, mobilization/demobilization, site preparation/teardown, and the operational/technical scope of work performed. Section 2.0 also compares the actual scope of work performed with the planned scope of work in general terms. Section 3.0

describes the technical approaches implemented to accomplish the operational and technical tasks of the project including sampling, analysis, waste transportation, and waste disposal. Section 4.0 describes the Health and Safety approaches implemented to accomplish the operational tasks of the project. Section 5.0 and 6.0 contain the quantity summary tables and verification analytical summary tables respectively. Appendix A depicts the Flow Charts showing work performance. Appendix B provides detailed descriptions of the work performed at each remedial location, as well as, tables and maps detailing the sampling and analysis. Appendix C contains the detailed descriptions of work performed on the easements for this project.

2.0 SCOPE OF WORK

The scope of work for this project was delineated by the documents USACE supplied to OHM entitled: Scope of Work for Contract DACA45-95-R-0015, Stack Emissions (Lead) Removal, Madison, Illinois.

The scope of work generally encompassed the following tasks:

- Preparation of site-specific plans
- Site administration and logistical support
- Mobilization and demobilization
- Site preparation and teardown
- Excavation, Backfill, and Compacting
- Turf
- Operational scope of work
- Waste transportation and disposal

2.1 PREPARATION OF SITE-SPECIFIC PLANS

OHM revised the site-specific project work plan (WP) from DO 17 to serve as a guideline describing how the work was to be performed in order to meet the requirements specified by USACE. The WP also included the chemical data acquisition plan (CDAP) and the location-specific health-and-safety plan (LSSHP).

Variances to the WP occurred during the project but were conducted only under authorization/direction of the USACE on-site representative(s). His/her purpose was to allow the project to function more efficiently while still remaining within all regulatory requirements. These variances are referenced and described in the relevant sections of this report.

The CDAP was prepared as a guideline to describe how, where, and how many samples would be collected. The laboratory analysis methods to be used, per the requirement of USACE's revised scope of services, were also outlined in the CDAP. In response to existing field conditions, this CDAP was amended to add the quality assurance project plan (QAPP) during the actual performance of work (see Section 2.6 for these amendments).

The LSSHP was prepared as a guideline describing the health and safety procedures which would be followed during the performance of the project. LSSHP addressed physical, chemical, and

environmental hazards unique to this project site. This LSSHP was amended prior to the project to allow remedial work to be performed by personnel wearing modified USEPA Level D personal protective equipment (PPE). The results of air monitoring indicated personnel could safely perform work at the remedial locations wearing poly tyvek suits, booties, gloves, hard hats, and safety glasses without respirators. Details pertaining to health and safety issues are discussed in Section 4.0, Health and Safety Summary.

2.2 SITE ADMINISTRATIONAL/LOGISTICAL SUPPORT

The project site administration was centrally located at # 10 Farrish in Madison, Illinois. Site administrative activities performed from this location included:

- Site Supervisor
- Cost tracking/reporting
- Health and Safety administration
- Waste tracking/documentation
- Field sampling/analytical support
- Field purchasing/subcontract management
- Logistical support

Prior to the physical work, logistical preparation activities were performed, including the following activities:

- Conduct a pre-construction meeting
- Verifying waste hauling licenses
- Meeting with property owners
- Locating utilities at necessary sites
- Establishing transportation routes
- Coordinating with local agencies and hospital

2.3 MOBILIZATION/DEMOBILIZATION

OHM performed mobilization of personnel and equipment primarily from its facility in O'Fallon, Missouri. A large percentage of the heavy equipment utilized on this project came from local vendors acting as subcontractors.

2.3.1 Subcontractors

Subcontractor activities were managed by the OHM project manager and site supervisor, and by USACE when necessary. Subcontractors were responsible for transportation, disposal, backfill material, sod and on-site equipment.

2.3.2 Permits

All necessary permits and licenses were secured before site mobilization. The transporter companies and disposal facilities were USEPA-licensed. Prior to mobilization, all on-site employees completed Occupational Safety and Health Administration (OSHA) 40-hour hazardous material training.

2.4 MOBILIZATION/DEMOBILIZATION

Sites were set up and/or torn down at each remedial lot.

2.4.1 Command Center

The command center served as the central location from which all personnel were dispatched to their respective work locations each day or as needed. The command center was located inside of a secured building and was equipped with computers, copiers, facsimile machine, telephones, and base radio. The rear of the building also served as a storage area for OHM's equipment, tools, and materials.

2.4.2 Remedial Locations

Site preparation was performed at each of the remedial locations. OHM set up decontamination points for personnel and equipment and exclusion zones were established prior to excavation. These exclusion zones were identified with orange snow fencing and yellow caution tape across existing fencing. They remained in place until backfill had been completed to a sufficient depth.

Excavation equipment used on the site was decontaminated prior to demobilization or backfill. Gross contamination was scraped from the machines before they were washed. As a dust control measure, the decontamination rinse water was collected and applied to the last load of contaminated soil.

2.5 OPERATIONAL SCOPE OF WORK PERFORMED

The excavation activities involved the removal of contaminated soils from the remedial sites. Restoration involved backfilling, seeding, and sodding of the sites after completing the remedial activities. The scope of work for this portion of the project is illustrated in Figure 2.1.1 The operations Flow Chart is depicted in Appendix A-1.

OHM's schedule for excavation was developed to facilitate logistical management and limit the time required to transport equipment and crews from location to location. During excavation activities, engineering controls and security measures, such as surrounding the exclusion zones with fluorescent orange polyvinyl chloride (PVC) barrier fencing, were employed to prevent cross contamination and unauthorized entry into exclusion zones.

Each of the stack emission sites had unique characteristics, which mandated particular methodologies of remediation.

2.5.1 Pre-construction Activities

Pre-construction activities for this portion of the project included the following items:

- Conducting a pre-construction meeting with USACE
- Issuing subcontracts
- Communication with Julie Corporation (the utilities' identification organization in Illinois) to locate potential underground utilities at the site
- Obtaining permits
- Obtaining soil samples for waste characterization
- Videotaping residential properties for restoration purposes

2.5.2 Construction Activities-Lots

The excavation techniques employed at each location varied according to location accessibility, depth, and extent of material. Minimization of disturbances to adjoining properties/areas was also a key consideration in performing each excavation. OHM used Bobcat mini-excavators, TL26, Takeuchi, TCM806 along with Kubota Tractors and manual removal methods.

Dust control was a major consideration. A storage system with pump and hose were available at all times to prevent fugitive emissions. Water trucks were also utilized to provide additional dust control and to transport water to sites for decontamination.

Most of the residential yards needed to have sod removed at varying depths of soil. Wastes were excavated using a track excavator, Takeuchi, and/or a Bobcat. At some locations, hand digging was necessary. Special soil was loaded into licensed waste hauler trucks for transportation to the disposal facility.

Most of the driveways contained aggregate soil mixtures. Most locations were accessible but required smaller equipment and hand digging. Non-hazardous waste (special waste) was classified analytically. The special waste was loaded into licensed haul trucks and sent to the disposal site.

2.5.4 Restoration

After excavation to predetermine depth had been achieved, OHM restored the location to preremedial conditions. Excavation areas were backfilled with clean soil and restoration was completed as required by the specifications. Sodding, seeding, and revegetation were performed when necessary.

2.5.5 Waste Removal

Wastes removed from the sites were transported to one of two locations. Milam RDF/Chain of Rocks. Figure A-2 in Appendix A shows the flow chart for T&D.

2.6 SAMPLING AND ANALYSIS

The following paragraphs detail the sampling and analysis tasks, as well as CDAP amendments/adjustments.

2.6.1 Sampling and Analysis Tasks

The sampling and analysis tasks for this project involved the following items:

- Street Sweeping
- Pre-characterization sampling and analysis of sites included as delineated by USACE
- Pre-characterization sampling and analysis of additional sites
- Resample (stack emission) as directed by USACE
- Backfill sampling

Street Sampling

OHM collected random grab samples from streets, as directed by USACE, for the purpose of determining the lead content of the street.

As per the scope of services issued to OHM by USACE, material at the residential sites exhibiting concentrations of total lead greater than 500 mg/kg were to be removed and disposed.

Samples were collected from one point in the front yard and one point in the back yard. Both samples collected were at least 10 feet from any structures if possible.

Site Pre-Characterization Sampling and Analysis

As the project progressed, the need to establish the level of effort anticipated for each upcoming site became much more apparent. The need to pre-characterize each of the remedial locations to establish reasonable estimates of non-hazardous waste requiring removal was made evident via an amendment to the CDAP. The site pre-characterization sampling and analysis efforts were applied to non-hazardous (stack emission) sites. The primary purpose of these efforts was to confirm or refute the potential contamination at each remedial location and to obtain an indication of the extent of contamination at sites with lead concentrations greater than 500 mg/kg. The most efficient and productive approaches to the pre-characterization sampling and analysis, which include the steps described in the following paragraphs, were ultimately developed for the residential lots.

Pre-characterization sampling and analysis at the residential lots included the establishment of two sample locations at each site. The two sample points were positioned at the center of the front and back yard of each location. One sample was then collected at the following depths from each sample location: 0 to 3 inches, 3 to 6 inches, and 6 to 12 inches.

The laboratory analysis of the samples followed the logic as below. The two samples representing the top 3-inch layer of each of the locations were analyzed for total lead and toxicity characteristic leaching procedure (TCLP) lead. The second and third set (representing 3 to 6 and 6 to 12 inch depths) were analyzed for total lead only.

This is depicted in Figure A-3 in Appendix A.

Pre-characterization of Additional Sites

Under authorization of USACE, OHM performed the pre-characterization sampling of additional sites over and above the original scope of services. The objective of this was to determine the potential presence of lead contamination with anticipation for the planning of remediation at these same sites. The technical approach for this task involved the same approaches as mentioned in the preceding paragraphs concerning pre-characterization.

2.6.2 CDAP Amendment/Adjustments

Development of the Sampling for Backfill Material

An amendment for the sampling and analysis of backfill was designed to show that incoming backfill material was clean to USEPA standards. This was done as a composite sample on every 1000 cubic yards of backfill and run for the following analysis:

- TCLP for Cd, Cr, Pb
- PAH-IEPA Levels
- Pesticides/PCB's
- TPH
- GRO
- DRO
- Total VOC's

2.7 TRANSPORTATION AND DISPOSAL

The transportation and disposal (T&D) of waste from the sites included the shipment of nonhazardous waste shipped to the Chain of Rocks facility/Milam facility. The special waste was transported by Garcia Trucking. The transportation of the waste was performed with tandem dump trucks.

2.7.1 Transportation of Waste

Each site was identified by an address which was written on the manifest. The site was then assigned a 5-digit manifest document number at the time of shipment. This system ensured the trucks origin was documented.

The State of Illinois requires each special waste shipment be on an all Illinois manifest. This allowed each shipment of special waste to also be cross-referenced with the preprinted Illinois manifest document.

2.7.2 Disposal of Wastes

This project involved the removal and disposal of special non-hazardous industrial waste (non-hazardous waste) which was primarily removed from residential locations. The objective of the non-hazardous waste excavation efforts was to remove all material exhibiting concentration of total lead above 500 mg/kg, but less than 5 mg/l, when analyzed by TCLP.

Disposal characterization of waste was determined by analyzing composite samples, as directed in Section 2.6. Pre-characterization analysis was done at each site to verify depth of lead contamination. The characterization of certain waste as non-hazardous was confirmed at each site with the performance of TCLP lead analysis of composite samples.

The disposal facility subcontracted to provide non-hazardous waste disposal was the Chain of Rocks facility/Milam. OHM obtained the approved waste profile by providing analytical that was previously performed under the Rapid Response Contract.

3.0 TECHNICAL APPROACH

The stated objective of this project was to excavate and dispose of lead contaminated soil in yards of residential communities as per the Record of Decision between the USEPA, IEPA, and the potentially responsible parties (PRPs) for the Superfund site.

This section describes the general approach implemented to complete the work in the residential lots. The methods implemented to perform the work on this project fall into one category:

• Residential lots (Non-Hazardous)

The operational effort extended was supported by the technical information that was gained through implementation of the following:

- CDAP amendment/adjustment
- Transportation and disposal, Appendix A-2

3.1 PRE-CONSTRUCTION ACTIVITIES

The pre-construction activities performed during this project were predominantly associated with obtaining disposal permits; obtaining transportation permits; preparing and delivering notifications of work to the public; attending public meetings; and identifying utilities at each remedial location. Many of these pre-construction activities were performed on an on-going basis as the project proceeded from one remedial location to the next.

The permits for the disposal of non-hazardous waste were obtained prior to shipment of the waste.

Before work progressed from one remedial location to the next, the identification of utilities was coordinated from the command center by OHM's safety supervisor. The identification of the utilities was coordinated with Julie Corporation. OHM's safety supervisor would telephone Julie Corporation and notify the organization of OHM's intention to perform work at a given site. Julie Corporation would then issue a "dig number" to OHM and notify all utility companies listed to provide service for the area of concern. Typically, the utility companies would mark the utilities on the site within 48 hours of OHM's initial contact with Julie Corporation.

OHM's subcontractors who performed the transportation of waste and equipment at and through the cities of Madison, Venice, and Granite City, Illinois City obtained required transportation permits.

3.2 SAMPLING AND ANALYSIS

The sampling and analysis tasks involved the following items:

- Laboratory confirmation sampling and analysis
- Pre-characterization sampling and analysis
- Backfill sampling

As per the direction of USACE, material at the residential sites exhibiting concentrations of total lead greater that 500 mg/kg were removed and disposed.

3.2.1 Pre-Characterization Sampling and Analysis

As the project progressed, the need to establish the level of effort anticipated for each upcoming site became much more apparent. The need to pre-characterize each of the remedial locations for establishing reasonable estimates of non-hazardous waste requiring removal was made evident through incorporation into the CDAP. The site pre-characterization sampling and analysis efforts were applied to non-hazardous (stack emission) sites. The primary purpose of the pre-characterization sampling was to confirm presence of non-hazardous waste meeting the action level. The most effective and productive approaches to the pre-characterization sampling and analysis were ultimately developed for the residential lots.

3.2.2 Technical Approach to Stack Emission Lots

The technical approach to the stack emission lots differed from the residential battery casing cleanups in the respect no confirmation sampling was necessary. The reason for this was due to previous sampling results yielding a pre-determined depth per USEPA. Consequently, yards were excavated to this pre-determined depth. In addition, all waste was shipped out as special-direct to a landfill.

3.3 CHEMICAL DATA ACQUISITION PLAN AMENDMENTS/ADJUSTMENTS

3.3.1 Development of the Sampling for Backfill Material

An amendment for the sampling and analysis of backfill material was designed to show that incoming backfill material was clean to USEPA standards. This was done as composite samples on every 1000 cubic feet of backfill and run for the following analysis:

- TCLP for Cd, Cr, Pb
- PAH-IEPA Levels
- Pesticides/PCB's
- TPH
- GRO
- DRO
- Total VOC's

3.4 TRANSPORTATION AND DISPOSAL

The T & D of waste removed from the sites included the shipment of non-hazardous waste by Garcia Trucking to Chain of Rocks Landfill/ Milam in Granite City, IL.

3.3.1 Transportation of Waste

Each site was identified by an address, which was written on the manifest. The site was then assigned a 5-digit manifest document number at the time of shipment. This system ensured the trucks origins were documented.

3.3.2 Disposal of Wastes

Disposal characterization of the waste was determined by analyzing composite samples, as described in Section 2.6. Verification of waste characterization was performed at each site through precharacterization efforts. The characterization of certain waste as non-hazardous was confirmed at each site with the performance of total lead and TCLP lead analysis of composite samples.

The disposal facility subcontracted to provide non-hazardous waste disposal was Chain of Rocks/Milam in Granite City, IL. OHM obtained the approved waste profile by providing analytical that was previously done under Rapid Response Contract.

4.0 HEALTH AND SAFETY SUMMARY

4.1 PROJECT SUMMARY AND CONCLUSIONS

4.1.1 <u>Summary</u>

The following summarizes the health and safety aspects of this project:

- Task-specific hazard evaluations were performed each day at each work site prior to the start of work
- Air monitoring data was used during this project to verify appropriate personal protection was being used for site conditions. Personnel medical monitoring was performed prior to and at the end of the project to determine lead levels in the blood.
- Perimeter samples indicated total lead concentration below the action limit established in the LSSHP. Although results obtained are "after the fact," no personnel or citizens were at risk to exposure at any time.
- Personnel air sampling data indicated no detectable reading for total lead. There were no recorded cases of personnel overexposure to ambient lead levels.

4.1.2 Conclusions

Following completion of the project, the OHM Health and Safety Department made the following conclusions:

- The LSSHP was effectively implemented to address the health and safety hazards associated with each phase of site operations and to meet the requirements set forth in 29 CFR 1910.120.
- The existing LSSHP is appropriate for future phases of work at this site involving the same work activities.
- Future work should be performed in Level D PPE with appropriate air monitoring to verify the selection of PPE. An action level of 30mg/m3 should be used to warrant controls. Once monitoring shows consistent reading below the action level, the amount and frequency of air monitoring may be appropriately limited/reduced.
- Special attention should be paid to prevent any recordable accidents and near misses during the course of future work. Routine tasks should be reviewed and evaluated for potential hazards.

4.2 SITE SAFETY AND HEALTH PLAN EVALUATION

A LSSHP was issued before the start of this project to address the health and safety hazards associated with each phase of site operations. The plan met the requirements of 29 CFR 1910.120. The phases of work addressed in the LSSHP include the following:

- Mobilization
- Installation of perimeter fence
- Soil sampling
- Excavation of contaminated soil
- Load-out of contaminated soil
- Backfill of excavation
- Restoration of disturbed areas
- Decontamination and demobilization

4.2.1 Provisions

Once on site, waste materials were designated to be directly loaded into dump trucks.

Provisions were made to address heavy equipment, excavation and other physical hazards. Hazards associated with vehicle and pedestrian traffic in work areas and roadways were controlled by the use of warning signs, Men at Work signs, and road guards to direct traffic.

4.2.2 Personal Protective Equipment

PPE visions were made to minimize exposure to lead contamination for personnel on site. Level D PPE included the following:

- Hard hat
- Safety glasses
- Steel-toed leather safety shoes/boots
- Poly tyvek coveralls
- Nylon booties (under) and Robar/Tingley boots (outer)
- Inner sample gloves, outer cloth or leather gloves

An action level of 15.0 mg/m3 of airborne lead, as determined by integrated sampling, was set by USACE to upgrade the level of PPE to Level C (including use of an air purifying respirator.) Air monitoring was performed for the duration of remedial activities to ensure proper PPE use.

4.3 SITE SAFETY

4.3.1 Accidents

Employee safety was OHM's first priority. After performing more than 157,454 man hours on

USACE
Granite City, Illinois
©1999 OHM Remediation Services Corp.

Project 19321 Final Report February 15, 1999 this project, OHM personnel suffered no OSHA-recordable accidents or injures.

4.3.2 Preventative Measures

A number of measures were taken on site to prevent accidents and injures. Daily safety meeting were held to discuss: hazards associated with upcoming work tasks; the use of specific tools and equipment; and other chemical, physical, and environmental hazards associated with site work. Task-specific hazard evaluations were performed each day at the work sites prior to the start of work.

Controls were used to eliminate the hazards associated with vehicle and pedestrian traffic near the work locations. Warning signs were posted and guards were used to direct traffic.

A heat stress prevention program was also instituted on site. Personnel heat stress monitoring was performed to prevent heat related illnesses during work in high ambient temperatures. Site workers= pulses, body temperatures, and blood pressures were taken before and after each break. Workrest schedules were determined by the results of this monitoring in accordance with the LSSHP heat stress monitoring criteria.

Specific work/rest regimens were established at the start of every work day based on the specific work conditions for that day (temperatures, time of day, amount of sun or shade, etc.) Breaks were taken in shady areas as designated throughout the work shift. Personnel removed PPE and were given cool liquids to drink (e.g., juice, water). Visual observation by a designated safety official was used to identify individuals exhibiting symptoms of heat-related illness and to take the necessary actions.

4.4 EXPOSURE MONITORING

4.4.1 Methodology

Air monitoring was performed to determine the ambient levels of total suspended particulates generated during excavation and to determine total ambient lead exposure for site personnel and perimeter emissions. At the start of each work day, wind direction was used to determine the placement of sampling instruments on site.

Personnel and perimeter samples were taken to determine the levels of total lead in the air of the personal breathing zone and at the site perimeter. Lead samples were collected and analyzed using NIOSH Method 7300 and battery-operated air sampling pumps (Gillian or equivalent) fitted with 37-millimeter (mm) mixed cellulose ester (MCE) filters (0.8-micron pore diameter).

4.4.2 Perimeter Sampling

Three perimeter samples were taken daily over the course of the work shift. One sample was taken upwind of site operations and two were taken downwind. Perimeter samples were taken above ground levels (approximately 4 to 5 feet in height) to characterize the breathing zone and to prevent contamination due to foot traffic. The pump flowrate was calibrated and set at approximately 20 liters

per minute for the duration of the task (about 8 hours.)

Samples were assigned identification numbers based on an established code. The analytical laboratory used was Environmetrics, 11401 Moog Drive, St. Louis, Missouri. Standard turnaround time for sample results was 24 to 48 hours by facsimile; original data was then returned by mail.

4.4.3 Personnel Sampling

Personnel air samples for lead were taken for a respective number of employees performing intrusive activities within the exclusion zone (one employee from each job category; at least two employees per day per site). The samples were taken in the person's breathing zone for the duration of the day's shift. Samples were collected at the end of the work day and sent to the analytical laboratory for analysis of total lead. A blank sample was included in shipment.

4.4.4 Medical Monitoring

Personnel blood lead levels were determined prior to and after the completion of work for this project.

5.0 QUANTITY SUMMARY TABLE

Quantities of material were tracked for each lot or site remediated. Table 5.1 presents a summary of these totals.

DACA45-5u-D-0014 D.O. 0004 Project 19321

QUANTITY SUMMARIES

		1	_	_	_			·—-	_		_	r	-	_		_						_			-	-			<u></u>	
Backfill	loads	2	7		6	2	2		53		8	7		2	2		1	6	14	14	7	2	3	2		5		4		
Topsoil	cu yd	19.52	76.29	41.42	59.58	52.81	69.47	49.31	176.35	133.70	53.02	64.20		21.15	18.29	15.59	50.28	94.65	38.46	99.68	18.44	25.38	9.81	9.02	55.38	63.78	116.38	79.68	49.40	63.97
CA-7	ton	27.74		8.91			14.01	28.12	15.57		14.29		300.008	40.38	15.86	14.16	24.41		57.5		42.3	26.19	14.83				14.2	17.03	24.29	14.38
CA-6	ton	37.67	18.24	37.47	49.17				113.15				403.33	55.97	14.95	28.67			258.97		41.45	44.12	43.18			266.44		15.58	25.87	109.43
Sod	sq yd	120	300	180	320	285	480	360	1260	780	435	360		120	120	180	240	540	4250	540	300	105	135	180	300	009	540	495	300	240
Special	cu yd	36.45	82.13	25.86	96.47	50.41	69.44	41.83	131.68	71.15	121.85	79.89	343.31	61.53	72.86	18.91	43.54	92.36	273.61	184.25	81.67	46.45	41.19	19.03	44.49	70.86	76.57	70.07	42.21	108.18
Site	Address	1918 Benton	2230 Benton	2232 Benton	1724/26 Chestnut	1746 Chestnut	1716 Cleveland	1733 Delmar	1201/15 Grand	1217/19 Grand	1231 Grand	1414 Grand	1718-24 Grand	1919/21 Grand	1923/25 Grand	1929/31 Grand	2204 Grand	919 lowa	1401 lowa	1405 lowa	1415 lowa	1417 lowa	1423 lowa	825 Madison	1230 Madison	1603 Maple	1607 Maple	1610 Maple	1614 Maple	1617 Maple

	2			5									8			5	8	5	9		10		12	15	231.00
	11.43	104.42	90.34	51.04	42.48	18.33		37.86		9.27	8.84	23.59	96.98	6.10	16.35	93.96	48.74	36.85	76.79	53.20	263.98		115.12	136.56	2947.22
	55.14		13.26		28.34	11.59	43.4	28.83	29.12	138.42	24.58	86.09		45.48	14.91	16.18	69.49	58.68	42.5		13.31	39.74	94.67	26.4	1594.36
-	51.65	15.12	25.56	28.58		29.33		13.64	42.06	275.24	84.75	201.19			28.78	84.79	27.76	14.55	54.04	27.2		14.41	13.24	25.17	2620.72
	120	465	420	320	240	180		120	STONE	09	09	09	360	120	09	287	300	300	360	360	006		720	006	21077.00
	63.91	63.31	44.71	57.59	23.08	36.06	18.73	45.15	16.14	155.23	112.65	151.37	107.97	31.29	39.09	128.13	107.43	61.12	145.48	58.05	164.39	21.35	183.86	201.65	4535.99
	1628 waple	1633 Maple	1635 Maple	1637 Maple	1643 Maple	1651 Maple	910 Niedringhaus	910 1/2 Niedringhaus	912 Niedringhaus	929 Niedringhaus	931 Niedringhaus	935 Niedringhaus	1632 Olive	1636 Olive	1638 Olive	1618 Spruce	1646 Spruce	1318/20 State	1344 State	1720 State	1725 State	1808/10 State	2005 14th	2007 14th	Total:

6.0 VERIFICATION ANALYTICAL SUMMARY TABLE

6.1 Stack Emission Sites

Stack emission sites were not sampled for verification. This was due to the fact that a predetermined depth for excavation was given to OHM by USACE for each stack emission site.

Stack emission sites are sampled for pre-characterization analysis. Depth's from Woodward/Clyde Sampling are being reviewed by the USEPA and may result in re-sampling.

7.0 PHOTO REPRESENTATION

Photographs and videocassettes documented all sites in all phases of the Granite City project. Each property was documented with before, during, and after photographs and videos. The following sections are representative of the various types of work performed during Phases 1, 2, and 3. Not all properties - only selected representative samples - are presented in this final report, in order to minimize the volume of paper.

1231 Grand (Page 7-2)

Top picture - Lot before excavation Middle picture - Lot during excavation Bottom picture - Lot after restoration/sod

935 Niedringhaus (Page 7-3)


Top picture - Lot before excavation Middle picture - Lot during excavation Bottom picture - Lot after restoration/sod


1725 State (Page 7-4)

Top picture - Lot before excavation

Middle picture - Lot during excavation

Bottom picture - Lot after excavation/finished to grade









APPENDIX A FLOW CHARTS


OPERATIONS FLOW JART



TATION AND DISPOSAL TECHNICAL EFFORT FOR TRANSH



TECHNICAL EFFORT FOR : MPLING



CRYTIQUE DALY ACTIVITIES WITH HSS. DISCUSS AND REVIEW PROBLEMS CALIBRATE NEEDED AR MONITORING PLANDS TURN IN DALY NOTES AND SITE MAP WITH PUMP LOCATIONS POST CALIBRATION OF PUMPS WEEKLY EQUIPMENT AND CARTREICK INSPECTIONS REMOVAL OF FAULTY EQUIPMENT ENCOUNTERED DURING THE DAYS ACTIVITIES SAFETY FLOV CHART ONGOING MONITORING OF PERSONNEL AND PUMPS ALL MANDATORY SAFETY EQUIPMENT SPOTTEDIE, FIRE EXTINGALISHERS, EYE WASH, FIRST AD STATION, ETC GENERATORS SPOTTED, GROUNDED AND TURNED ON SAFETY TECHS ISSUE PERSONAL PUMPS HAND OUT MAPS AND DAILY ASSIGNMENTS PLACE PERIMETER PUMPS SITE SETUP JULE SITES FOR OPERATIONS AS NEEDED REVIEW PAPERWORK PREPARE AND IMPLEMENT ANY CHANGES TO HASP PICKAGE AND SEND OFF ALL SAMPLES SAFETY SUPERVISOR ONGOING CHECKS OF FIELD ACTIVITY PREPARE DAILY SAFETY MEETING DALY SAFETY NEETING HELD FOR CREW

TAKE CARE OF ANY CONCERNS OR PROBLEMS OF PROPERTY OWNERS BEFORE, DURING, AND AFTER ANY OF WORK RESOLVE ANY RESTORATION PROBLEMS WITH OWNERS / REVIEW FILM / PICTURES TAKE FINAL PICTURES OF PROPERTY COPY AND FILE ALL PAPERMORK FOR COMPLETED SITE SCHEDULE VACCUM PROCEDURE IF OWNER APPROVES WALK PROPERTY WITH OWNER FOR COMPLETION FORM SIGNATURE IF NEEDED KEEP WALL MAP UPDATED KEEP UPDATED LIST OF HOMES READY TO REMEDIATE KEEP UPDATED LIST OF HOMES TO VACUUM JULIE CALL IN AND UPDATES DISCUSS SNY CHANGES OF PROPERTY AGREEMENT WITH OWNER WALK PROPERTY WITH EXCAVITION FOREMAN AND DISCUSS PROPERTY AGREEMENT CONTACT OWNER OF PROPERTY BEFORE WE ARRIVE ON SITE TO SETUP CONTACT OWNERS OF PROPERTIES APPROVED TO BE FEMELATED TO SETUP APPONTMENTS TO DO PROPERTIY AGREEMENTS MEET WITH OWNER WALK PROPERTY AD WRITE IP PROPERTY AGREEMENT SITE COORDINATOR PHOTOCOPY AND FILE ACCESS AGREEMENTS WHEN RETURNED ANSWER QUESTIONS FROM PROPERTY OWNERS WHO CALL MAIL OUT ACCESS AGREEMENTS TRACK DOWN OWNERS OF RETURNED UNCLAINED ACCESS ACCESS

LOW CHART

SITE COORDINATOR

PICTURE DOCUMENTATION IN ALBUM OF COMPLETED PROPERTY

VIDEO AND PICTURE PROPERTY AND BASEMENT BEFORE EXCAVATION

DISCUSS INSIDE ACCESS AND VACCUM PROCEDURE WITH HOMEOWNER

RESEARCH PROPERTIES FOR ZONING

A-5

APPENDIX B REMIDIAL LOCATION WORK DESCRIPTION

APPENDIX B - REMEDIAL LOCATION WORK DESCRIPTIONS

1918 Benton
2230 Benton
2232 Benton
1724/26 Chestnut
1746 Chestnut
1716 Classaland

1716 Cleveland 1733 Delmar

1201/15 Grand

1217/19 Grand

1231 Grand 1414 Grand

1718-24 Grand 1919/21 Grand

1923/25 Grand 1929/31 Grand

2204 Grand

919 Iowa

1401 Iowa

1405 Iowa

1415 Iowa

1417 Iowa

1423 Iowa

825 Madison 1230 Madison

1230 Manie 1603 Manie

1603 Maple

1607 Maple

1610 Maple

1614 Maple

1617 Maple

1628 Maple

1633 Maple 1635 Maple

1635 Maple

1637 Maple 1643 Maple

1043 Maple 1651 Maple

1651 Maple

910 Niedringhaus

910 ½ Niedringhaus 912 Niedringhaus 929 Niedringhaus

931 Niedringhaus

935 Niedringhaus 1632 Olive

1636 Olive 1636 Olive 1638 Olive 1618 Spruce 1646 Spruce

1318/20 State 1344 State

1720 State 1725 State 1808/10 State

2005 14th 2007 14th

USACE
Granite City, Illinois
©1999 OHM Remediation Services Corp.

\sim		
•		

1918 Benton

Action Date: 03-03-97 Loadout: 03-04-97

Restoration Begins: 03-05-97 Restoration Completed: 03-11-97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 6 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 47.39 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:
 - *TL-26

*Kotuata

- *17-KW
- *X331
- *Subcontractors:

*WMI

-landfill

EASEMENT INFORMATION

This easement was completed after the Temporary Restraining Order (TRO) was lifted.

QUANTITY SUMMARY FOR

1918 Benton

į	SPECIAL	BACKFILL	TOPSOIL	SOD OR	CA-6	CA-7	SAND	CONCRETE	OTHER
	WASTE	(LOADS)	(TONS)	SEED	(TONS)	(TONS)	(TONS)	1	
	47.39	2	25.38	120	37.67	27.74			

Sampling Analysis Project #19321

0 - 3" Front and Back A PPM No. PPM No. Street/Number Address

PPM No.

B PPM No. 3 - 6" Front and Back B PP S B PPM Š

PPM No. 6 - 12" Front and Back
C C C
PPM PPM PPP
No. No. No

Depth Excav. (inch)

382

187

987


533

1110

692

1918 Benton

ဖ



X = SAMPLE POINT

1918 BENTON

TOTAL DEMINSIONS

108'X60'



Drawn By: Checked By:

Date: 6/5/97 Approved By:

Scale: NTS Drawing No:



2230 Benton

Action Date: 12-10-06 Loadout: 12-11-96

Restoration Begins: 12-14-96 Restoration Completed: 12-16-96

- *Stack emission sites were not sampled for verification due toe the fact that a predetermined depth for excavation was given to OHM by USEPA.
- *An excavation depth of 12 inches was established by USEPA prior to work commencing.
- *The excavation of special waste yielded a total of 82.13 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:
 - *TL-26 Takeuchi
 - *17-KW Generator
 - *Bobcat X331
- *Subcontractors:
 - *WMI landfill
 - *Prochnow Sod

EASEMENT INFORMATION

This easement was completed after the Temporary Restraining Order (TRO) was lifted.

QUANTITY SUMMARY FOR

2230 BENTON

SPECIAL	BACKFILL	TOPSOIL	CA-6	CA-7	SAND	SOD OR	CONCRETE	OTHER
WASTE	(LOADS)	(TONS)	(TONS)	(TONS)	(TONS)	SEED		
82.13	7	76.29	18.24			300		

Sampling Analysis Project #19321

A PPM 0 - 3" Front and Back A PPM A PPM Š. Street/Number Address

3 - 6" Front and Back

∞	Wdd	No.	
8	PPM	No.	
ω	Mdd	No.	

	ľ
×	١
Back	l
ä	H
σ	l
and	ı
_	l
9	ľ
5	l
щ	i
72	r
$\ddot{-}$	l
•	ı
9	ŀ
	ı
	ı
	Ĺ

ပ	PPM	No.
ပ	PPM	No.
၁	Wdd	No.

Depth Excav. (inch)

12

581 37


811

461

745

1640

2230 Benton



X = SAMPLE POINT

2230 BENTON

TOTAL DEMINSIONS

96'X67'



Drawn By: JG	Checked By:
Date: 5/29/97	Approved By:
Scale: NTS	Drawing No:

•

2232 Benton

Action Date: 12-10-96 Loadout: 12-11-96

Restoration Begins: 12-13-96 Restoration Completed: 12-14-96

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 3 inches was established by USACE prior to work commencing.
- *The excavation of special waste yield a total of 25.86 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:
 - *TL-26
 - *17-KW
 - *X331
- *Subcontractors:
 - *WMI

-landfill

*Prochnow

-sod

EASEMENT INFORMATION

This easement was completed after the Temporary Restraining Order (TRO) was lifted.

QUANTITY SUMMARY FOR

2232 Benton

SPECIAL	BACKFILL	TOPSOIL	SOD OR	CA-6	CA-7	SAND	CONCRETE	OTHER
WASTE	(LOADS)	(TONS)	SEED	(TONS)	(TONS)	(TONS)	_	
25.86		53.85	180	37.48	8.91			

Sampling Analysis Project #19321

A PPM PPM No. Street/Number Address

A PPM 0 - 3" Front and Back

3ac				
6" Front and Back	В	Wdd	No.	
3 - 6"	В	PPM	No.	
	_	<u> </u>		}

Back	B
Front and	8
3 - 6"	8

100	В	PPM	No.	
ייים בייים	В	PPM	No.	
)	В	PPM	No.	

Back	ပ	Ndd
12" Front and B	၁	PPM
6 - 12"	၁	Mdd

Back	ပ	Wdd	No.
ront and	ပ	PPM	No.
6 - 12" F	O	M	0.

Depth Excav. (inch)

ی	dd	No	,,,,
	Σ		,

29

391

22


806

614


2232 Benton

153

က



2232 BENTON



<u> </u>			

1724/26 Chestnut

Action Date: 12-05-96 Loadout: 12-07-96

Restoration Begins: 12-07-96 Restoration Completed: 12-11-96

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 12 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 96.47 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:
 - *TL-26
 - *17-KW
 - *X331
- *Subcontractors:
 - *WMI

-landfill

*Prochnow Landscaping

-sod

EASEMENT INFORMATION

This easement was completed after the Temporary Restraining Order (TRO) was lifted.

QUANTITY SUMMARY FOR

1724/26 Chestnut

SPECIAL	BACKFILL	TOPSOIL	SOD OR	CA-6	CA-7	SAND	CONCRETE	OTHER
WASTE	(LOADS)	(TONS)	SEED	(TONS)	(TONS)	(TONS)		
96.47	9	77.45	320	49.17				

Sampling Analysis Project #19321


3ack	۷	PPM	N S
0 - 3" Front and Back	¥	Wdd	No.
0 - 3"	٧	Mdd	No.
		Street/Number	Address

	L,		
⋖	PPM	No.	
∢	PPM	No.	606 1420
⋖	Mdd	No.	578 524
	Street/Number	Address	1724/26 Chestnut

3ack	၁	PPM	No.
12" Front and Back	၁	Mdd	No.
6 - 12"	၁	PPM	No.
:			

3 - 6" Front and Back

	Depth	Excav.	(inch)	12
		5		
-	၁	PPM	No.	342
	ပ	Mdd	No.	497 726 1400
	၁	Mdd	No.	309 81 50
				·
	8	PPM	No.	13
	8	Mdd	No.	529 1070 70
	8	PPM	No.	152 201 73
				İ
	A	Mdd	No.	
	A	PPM	No.	606 1420
,	Π		П	



X = SAMPLE POINT

1724/26 CHESTNUT

TOTAL

DEMINSIONS

...

110'X54'



Drawn By: JG	Checked By:
Date: 5/29/97	Approved By:
Scale: NTS	Drawing No:

		•
,		
\sim		

1746 Chestnut

Action Date: 12-02-96 Loadout: 12-03-96

Restoration Begins: 12-03-96 Restoration Completed: 12-10-96

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 6 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 50.41 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:
 - *TL-26
 - *17-KW
 - *X331
- *Subcontractors:
 - *WMI
 - -landfill
 - *Prochnow Landscaping
 - -sod

EASEMENT INFORMATION

This easement was completed after the Temporary Restraining Order (TRO) was lifted.

QUANTITY SUMMARY FOR

1746 Chestnut

SPECIAL	BACKFILL	TOPSOIL	SOD OR	CA-6	CA-7	SAND	CONCRETE	OTHER
WASTE	(LOADS)	(TONS)	SEED	(TONS)	(TONS)	(TONS)		
50.41	2	68.65	285					

Sampling Analysis Project #19321

No. 0 - 3" Front and Back PPM No. PPM No. Street/Number Address

3 - 6" Front and Back

8	Wdd	No.
В	Mdd	No.
В	Mdd	No.

쑹	
ga	I
둳	I
and	
ront	I
ır.	
12	
	ı
Ψ	ı

יים וויים במסע	ပ	Mdd Mdd	No. No.
7	ပ	PPM	No.

Depth Excav. (inch)

9

350

446


811

585

684

517

1746 Chestnut



X = SAMPLE POINT

1746 CHESTNUT

TOTAL DEMINSIONS

108'X39'

OHM Corporation
Findley, Ohio

Drawn By: JG	Checked By:
Date: 5/30/97	Approved By:
Scale: NTS	Drawing No:

•		
•		
× 2		
\sim		

1716 Cleveland

Action Date: 11-13-96 Loadout: 11-16-96

Restoration Begins: 11-16-96 Restoration Completed: 12-14-96

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 6 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 69.44 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:
 - *TL-26
 - *17-KW
 - *X331
- *Subcontractors:
 - *WMI
 - -landfill
 - *Prochnow Landscaping
 - -sod

QUANTITY SUMMARY FOR

1716 Cleveland

-	SPECIAL	BACKFILL	TOPSOIL	SOD OR	CA-6	CA-7	SAND	CONCRETE	OTHER
	WASTE	(LOADS)	(TONS)	SEED	(TONS)	(TONS)	(TONS)		
į	69.44	2	90.31	480		14.01			

Sampling Analysis Project #19321

0 - 3" Front and Back PPM No. Street/Number Address

A PPM No. PPM No.

ack	8	PPM	No.	
6" Front and Back	В	PPM	No.	
3 - 6"	8	PPM	No.	

720

450

590

1400

1716 Cleveland

3ack	၁	PPM	No.
12" Front and Back	၁	PPM	No.
6 - 12"	၁	PPM	No.
	, ,		

PPM	No.	480
PPM	No.	270

9

Depth Excav. (inch)

1733 Delmar

Action Date: 11-18-96 Loadout: 11-19-96

Restoration Begins: 11-20-96 Restoration Completed: 11-21-96

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 3 inches was established by USACE prior to work commencing.
- *The excavation of special waste yield a total of 41.83 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:
 - *TL-26
 - *17-KW
 - *X331
- *Subcontractors:
 - *WMI

-landfill

*Prochnow

-sod

QUANTITY SUMMARY FOR

1733 Delmar

SPECIAL	BACKFILL	TOPSOIL	SOD OR	CA-6	CA-7	SAND	CONCRETE	OTHER
WASTE	(LOADS)	(TONS)	SEED	(TONS)	(TONS)	(TONS)		
41.8	3	64.1	360		28.12			

Sampling Analysis Project #19321

0 - 3" Front and Back Street/Ni

۷	PPM	No.	
4	PPM	No.	320 510
٧	Mdd	No.	830 460
	Street/Number	Address	1733 Delmar

3ack	8	Wdd	No.
6" Front and Back	8	PPM	No.
3 - 6"	8	PPM	No.

			_
3ack	၁	Mdd	No.
12" Front and Back	ပ	PPM	No.
6 - 12"	၁	Mdd	No.
•			

3ack	၁	PPM	No.
12" Front and Back	ပ	PPM	No.
6 - 12"	၁	Mdd	No.
			_

Depth Excav. (inch)


က

360

170 22

52 250

480 200



X = SAMPLE POINT

1733/35 DELMAR

TOTAL DEMINSIONS

113'X39'

OHM Corporation
Findley, Ohio

Drawn E	JG	Checked By:
Date: 5/30/9)7	Approved By:
Scale:	NTS	Drawing No:

1201/15 Grand

Action Date: 01-28-97 Loadout: 02-03-97

Restoration Begins: 02-03-97 Restoration Completed: 02-12-97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 3 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 131.68 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:
 - *TL-26
 - *17-KW
 - *X331
- *Subcontractors:

QUANTITY SUMMARY FOR

1201/15 Grand

SPECIAL	BACKFILL	TOPSOIL	SOD OR	CA-6	CA-7	SAND	CONCRETE	OTHER
WASTE	(LOADS)	(TONS)	SEED	(TONS)	(TONS)	(TONS)		
131.68	53	229.25	1260	113.15	15.57			

Sampling Analysis Project #19321

0 - 3" Front and Back A PPM ON PPM No. Street/Number Address

PPM No. 509 710

1201/15 Grand

3 - 6" Front and Back

	8	Mdd	No.
	В	Wdd	No.
,	В	PPM	No.

sack	၁	Wdd	No.
12" Front and Back	၁	PPM	No.
6 - 12"	၁	Mdd	No.


Depth Excav. (inch)

က

168

368

300



X = SAMPLE POINT

1201/15 GRAND TOTAL

DEMINSIONS

120'X174'

OHM Corporation
Finding, Ohio

Drawn By: JG	Checked By:
Date: 5/30/97	Approved By:
Scale: NTS	Drawing No:

\sim		

1217/19 Grand

Action Date: 02-17-97 Loadout: 02-19-97

Restoration Begins: 02-25-97 Restoration Completed: 03-06-97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 3 inches was established by USACE prior to work commencing.
- *The excavation of special waste yield a total of 71.15 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:
 - *TL-26
 - *17-KW
 - *X331
- *Subcontractors:

*WMI

-landfill

QUANTITY SUMMARY FOR

1217/19 Grand

	BACKFILL (LOADS)		SOD OR SEED	CA-6 (TONS)	CA-7 (TONS)	SAND (TONS)	CONCRETE OTHER
71.15		173.81	780	(TOILO)			

Sampling Analysis Project #19321

Street/Number Address

A PPM 494 **507** 0 - 3" Front and Back A PPM S 484 150 A PPM No. 467 320 1217/19 Grand

3 - 6" Front and Back B

PPM ov PPM No. **634** 200 PPM No. 367 130

6 - 12" Front and Back

ပ	Wdd	No.	
ပ	PPM	No.	
ပ	PPM	No.	


Depth Excav. (inch)

127 87


233 299

216 460

က



TOTAL DIMENSIONS: 90' X 121'



-			
\sim			
\sim			
N .			
$\overline{}$			

1231 Grand

Action Date: 11-12-96 Loadout: 11-15-96

Restoration Begins: 11-15-96 Restoration Completed: 12-17-96

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 12 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 121.85 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:
 - *TL-26
 - *17-KW
 - *X331
- *Subcontractors:
 - *WMI
 - -landfill
 - *Prochnow Landscaping
 - -sod

QUANTITY SUMMARY FOR

1231 Grand

SPECIAL	BACKFILL	TOPSOIL	SOD OR	CA-6	CA-7	SAND	CONCRETE	OTHER
WASTE	(LOADS)	(TONS)	SEED	(TONS)	(TONS)	(TONS)		
121.85	8	68.93	435		14.29			

Sampling Analysis Project #19321

•	0 - 3"	0 - 3" Front and Back	3ack
	٧	A	
Street/Number	PPM	PPM	Ы
Address	No.	No.	Z


м —	20	20
ррм ррм	PPM	PPN
lo.	No.	No.

3ack	၁	PPM	No.
12" Front and Back	၁	PPM	No.
6 - 12"	၁	PPM	No.

Depth Excav. (inch)

၁	PPM	No.	
C	PPM	No.	

1231 Grand



_	
-	
\sim \sim	
\mathbf{C}	
\sim	
\sim	

1414 Grand

Action Date: 12-09-96 Loadout: 12-09-96

Restoration Begins: 12-14-96 Restoration Completed: 12-16-96

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 12 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 79.89 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:
 - *TL-26
 - *17-KW
 - *X331
- *Subcontractors:
 - *WMI

-landfill

*Prochnow Landscaping

-sod

EASEMENT INFORMATION

This easement was completed after the Temporary Restraining Order (TRO) was lifted.

QUANTITY	SUMMARY	FOR
-----------------	---------	-----


1414 Grand

SPECIAL	BACKFILL	TOPSOIL	SOD OR	CA-6	CA-7	SAND	CONCRETE	OTHER
WASTE	(LOADS)	(TONS)	SEED	(TONS)	(TONS)	(TONS)		
79.89	7	83.46	360			!		


No. 6 - 12" Front and Back O PPM S C PPM Š PPM No. m 3 - 6" Front and Back B B W 0 - 3" Front and Back Sampling Analysis Project #19321 Street/Number Address

Depth Excav. (inch) 12 270 704 626 1120 PPM No. PPM No. PPM No. 929 1550 A PPM ON

1414 Grand



X = SAMPLE POINT



-		

1718/20/22/24 Grand

Action Date: 01-07-97 Loadout: 01-24-97

Restoration Begins: 02-03-97 Restoration Completed: 02-11-97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 12 inches was established by USACE prior to work commencing.
- *The excavation of special waste yield a total of 343.31 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:
- *Subcontractors:

EASEMENT INFORMATION

This easement was completed after the Temporary Restraining Order (TRO) was lifted.

QUANTITY SUMMARY FOR

1718/20 Grand

SPECIAL	BACKFILL	TOPSOIL	SOD OR	CA-6	CA-7	SAND	CONCRETE	OTHER
WASTE	(LOADS)	(TONS)	SEED	(TONS)	(TONS)	(TONS)		
343.31				403.33	300.06			

Sampling Analysis Project #19321

PPM No. 0 - 3" Front and Back A PPM PPM No. Street/Number Address

3 - 6" Front and Back

B PPM No. B PPM No. PPM No.

PPM No. 6 - 12" Front and Back
C C C
PPM PPM PP
No. No. No. No.

563

Depth Excav. (inch)

12

736


841

709

801

1718/24 Grand

334



X = SAMPLE POINT

TOTAL DEMINSIONS . 125'X108' OHM Corporation
Findley, Ohio

Drawn By: JG	Checked By:
Date: 5/29/97	Approved By:
Scale: NTS	Drawing No:

	_·	
-		
$\overline{}$		
× 2		
\smile		
<		

1919/21 Grand

Action Date: 02-03-97 Loadout: 02-07-97

Restoration Begins: 02-08-97 Restoration Completed: 02-11-97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 6 inches was established by USACE prior to work commencing.
- *The excavation of special waste yield a total of 61.53 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:
 - *TL-26
 - *17-KW
 - *X331
- *Subcontractors:
 - *WMI

-landfill

*Turf Mountain

-sod

EASEMENT INFORMATION

This easement was completed after the Temporary Restraining Order (TRO) was lifted.

QUANTITY SUMMARY FOR

1919/21 Grand

5	SPECIAL	BACKFILL	TOPSOIL	SOD OR	CA-6	CA-7	SAND	CONCRETE	OTHER
	WASTE	(LOADS)	(TONS)	SEED	(TONS)	(TONS)	(TONS)		
_	61.53	2	27.5	120	55.97	40.38			

Sampling Analysis Project #19321

0 - 3" Front and Back

	∢	∢	∢
Street/Number	PPM	PPM	Mdd
Address	No.	No.	No.

3ack	8	Wdd	711
6" Front and Back	В	Wdd	~14
3 - 6"	8	Mdd	1

		_		1
, according	8	Wdd	No.	
ו טוג מוט במטי	В	PPM	No.	
0	8	Wdd	No.	

3ack	၁	PPM	No.
12" Front and Back	၁	PPM	No.
6 - 12"	၁	Mdd	No.

Depth Excav. (inch)

1919/21 Grand

1923/25 Grand

Action Date: 02-11-97 Loadout: 02-13-97

Restoration Begins: 02-13-97 Restoration Completed: 02-15-97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 12 inches was established by USACE prior to work commencing.
- *The excavation of special waste yield a total of 72.86 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:
 - *TL-26

*Kobata

- *17-KW
- *X331
- *Subcontractors:

*WMI

-landfill

*Turf Mountain

-sod

EASEMENT INFORMATION

This easement was completed after the Temporary Restraining Order (TRO) was lifted.

QUANTITY SUMMARY FOR

1923/25 Grand

	SPECIAL	BACKFILL	TOPSOIL	SOD OR	CA-6	CA-7	SAND	CONCRETE	OTHER
	WASTE	(LOADS)	(TONS)	SEED	(TONS)	(TONS)	(TONS)		
-	72.86	2	23.78	120	14.95	15.86			

Sampling Analysis Project #19321

A PPM 0 - 3" Front and Back No. PPM No. Street/Number Address

3 - 6" Front and Back

	В	рРМ	No.	
	В	PPM	No.	
)	В	PPM	No.	

3ack	ပ	Wdd	No.
12" Front and Back	၁	Wdd	No.
6 - 12"	၁	Mdd	No.
,			

Back	ပ	PPM	No.
Front and	၁	PPM	No.
12"			

Depth Excav. (inch)

12

214

797

446


1330


759

1250

1923/25 Grand

100	၁	Wdd	No.	
1		M).	i





1929/31 Grand

Action Date: 02-13-97 Loadout: 02-13-97

Restoration Begins: 02-14-97 Restoration Completed: 02-17-97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 6 inches was established by USACE prior to work commencing.
- *The excavation of special waste yield a total of 18.91 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:
 - *TL-26

*Kobata

- *17-KW
- *X331
- *Subcontractors:

*WMI

-landfill

*Turf Mountain

-sod

EASEMENT INFORMATION

This easement was completed after the Temporary Restraining Order (TRO) was lifted.

QUANTITY SUMMARY FOR

1929/31 Grand

-	SPECIAL	BACKFILL	TOPSOIL	SOD OR	CA-6	CA-7	SAND	CONCRETE	OTHER
	WASTE	(LOADS)	(TONS)	SEED	(TONS)	(TONS)	(TONS)		
Ĺ	18.91		20.27	180	28.67	14.16			

Sampling Analysis Project #19321

	.0 - 3	0 - 3" Front and Back	3ack
	4	٧	1
Street/Number	PPM	Wdd	Ыd
Address	No.	No.	Ž

	3 - 6"	3 - 6" Front and Back	3ack
4	80	B	8
Mdc	PPM	Wdd	dd
Š	No.	No.	N

Depth Excav. (inch)

9

284

236

194

324

465

583

464

655

1929/31 Grand

$\overline{}$		
	·	
X		

2204 Grand

Action Date: 12-31-96 Loadout: 01-02-97

Restoration Begins: 01-02-97 Restoration Completed: 01-03-97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 6 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 43.54 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:
 - *TL-26
 - *17-KW
 - *X331
- *Subcontractors:
 - *WMI

-landfill

*Turf Mountain

-sod

EASEMENT INFORMATION

This easement was completed after the Temporary Restraining Order (TRO) was lifted.

QUANTITY	SUMM	IARY	FOR
----------	------	------	------------

2204 Grand

SPECIAL	BACKFILL	TOPSOIL	SOD OR	CA-6	CA-7	SAND	CONCRETE	OTHER
WASTE	(LOADS)	(TONS)	SEED	(TONS)	(TONS)	(TONS)		
43.54	1	65.36	240		24.41			

Sampling Analysis Project #19321

Š	No.	No.	Address
Ndd	PPM	Wdd	Street/Number
٧	A	٧	
200	טייט שטייו שייט וייט יי	0-0	

•	0 - 3	0 - 3" Front and Back	Sack	3 - 6'	3 - 6" Front and Back	3ack
	4	4	4	æ	В	6
Street/Number	МЧЧ	Mdd	PPM	PPM	Mdd	Mdd
Address	No.	No.	No.	No.	No.	No.
7 7 0 0 0	, F	70		166	7.10	
2204 Grand	2	2		400	4/8	
	388	423		502	351	
	549	548	1790	460	505	483
	661	429		530	385	

Back	၁	MQQ
12" Front and E	၁	MOO
6 - 12"	ပ	Mac

		_		
ack	၁	PPM	No.	
12" Front and Back	၁	Mdd	No.	
6 - 12"	ပ	Wdd	No.	

Depth Excav. (Inch)

9

	၁ ၁	Mdd Mdd Mdd	No. No. No.	110 276	386 140	236 230 306	426 233
•	ပ	Ы	No	11(386	23(42

•			
\smile			

919 Iowa

Action Date: 12-10-96 Loadout: 12-11-96

Restoration Begins: 12-11-96 Restoration Completed: 12-16-96

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 12 inches was established by USACE prior to work commencing.
- *The excavation of special waste yield a total of 92.36 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:
 - *TL-26
 - *17-KW
 - *X331
- *Subcontractors:
 - *WMI
 - -landfill
 - *Brockmier

QUANTITY	SUMMA	RY FOR
-----------------	--------------	--------

919 lowa

SPECIAL	BACKFILL	TOPSOIL	SOD OR	CA-6	CA-7	SAND	CONCRETE	OTHER
WASTE	(LOADS)	(TONS)	SEED	(TONS)	(TONS)	(TONS)		
92.36	9	123.05	540					

Sampling Analysis Project #19321

3ack	A	PPM	No.
0 - 3" Front and Back	A	PPM	No.
0 - 3"	4	PPM	No.
		Street/Number	Address

3ack	8	Wdd	No.	
6" Front and Back	8	PPM	No.	
3 - 6"	m	Mdd	No.	

917

229

724

2030

289

919 lowa

6 - 12" Front and	၁	₽₽M	No.	
6 - 12	ပ	PPM	No.	
3ack	æ	PPM	No.	
it and Back	8	PM	ō.	

		_	
3ack	၁	Wdd	No.
12" Front and Back	၁	PPM	No.
6 - 12"	၁	PPM	No.
		<u> </u>	

Depth Excav. (inch)

	_
Back	
and	l
ă	ľ

၁	₩dd	No.	
ပ	PPM	Š.	

ပ	Mdd	No.	733 494
ပ	PPM	No.	141 288

1401 Iowa

Action Date: 02-06-97 Loadout: 02-06-97

Restoration Begins: 02-12-97 Restoration Completed: 02-14-97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 12 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 273.61 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:
 - *TL-26
 - *17-KW
 - *X331
- *Subcontractors:
 - *WMI

-landfill

EASEMENT INFORMATION

This easement was completed after the Temporary Restraining Order (TRO) was lifted.

QUANTITY SUMMARY FOR

1401 lowa

-	SPECIAL	BACKFILL	TOPSOIL	SOD OR	CA-6	CA-7	SAND	CONCRETE	OTHER
	WASTE	(LOADS)	(TONS)	SEED	(TONS)	(TONS)	(TONS)		
	273.61	14	50	420	258.97	57.5			

Sampling Analysis Project #19321


3ack	٧	Mdd	No.
0 - 3" Front and Back	Α	PPM	No.
0 - 3"	4	Wdd	No.
		Street/Number	Address

12" Front and Back	၁	PPM P	No.	
6 - 12" Fror	၁	H Wdd	No.	
쑹	ω	PPM	No.	

ack	ပ	PPM	No.
12" Front and Back	၁	PPM	No.
6 - 12"	၁	Mdd	No.

Depth Excav. (inch)

1401 lowa



X = SAMPLE POINT

TOTAL
DEMINSIONS
122'X95'

OHM Corporation
Finday, Ohio

Drawn By: JG	Checked By:
Date: 5/30/97	Approved By:
Scale: NTS	Drawing No:

1405 Iowa

Action Date: 01-29-97 Loadout: 02-01-97

Restoration Begins: 02-01-97 Restoration Completed: 02-19-97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 12 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 184.25 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:
 - *TL-26
 - *17-KW
 - *X331
- *Subcontractors:
 - *WMI

-landfill

- *Petago
 - -sod
- *C. Grantham

EASEMENT INFORMATION

This easement was completed after the Temporary Restraining Order (TRO) was lifted.

QUANTITY SUMMARY FOR

1405 lowa

SPECIAL	BACKFILL	TOPSOIL	SOD OR	CA-6	CA-7	SAND	CONCRETE	OTHER
WASTE	(LOADS)	(TONS)	SEED	(TONS)	(TONS)	(TONS)		
184.25	14	116.56	540					

Sampling Analysis Project #19321

	٧	A	٧
Street/Number	Mdd	PPM	Mdd
Address	No.	No.	No.

	B	₽PM PPM	No.	610	496
ack	A	PPM	No.		
U - 3" Front and Back	٧	Mdd	No.	208	743
0 - 3	4	Mdd	No.	296	587
		rmber	SS		

1405 lowa

3ack	၁	Mdd	No.
12" Front and Back	၁	PPM	No.
6 - 12"	ပ	PPM	No.
,			

3ack	၁	PPM	No.
12" Front and Back	င	PPM	No.
6 - 12"	၁	Mdd	No.

B B No.

B PPM No.


459 **718**

3 - 6" Front and Back

Depth Excav. (inch)

12

ပ	Mdd	No.	233
ပ	PPM	No.	7410 552



X = SAMPLE POINT

1405 IOWA

TOTAL DEMINSIONS 131'X54'



Drawn By:	Checked By:
Date: 11/18/96	Approved By:
Scale: NTS	Drawing No:

		-	-	
X 2				
_				
X 2				
$\overline{}$				

1415 Iowa

Action Date: 02-15-97 Loadout: 02-18-97

Restoration Begins: 02-18-97 Restoration Completed: 02-19-97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 12 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 81.67 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:
 - *TL-26
 - *17-KW
 - *X331
- *Subcontractors:
 - *WMI

-landfill

*Turf Mountain

-sod

EASEMENT INFORMATION

This easement was completed after the Temporary Restraining Order (TRO) was lifted.

QUANTITY SUMMARY FOR

1415 lowa

SPECIAL	BACKFILL	TOPSOIL	SOD OR	CA-6	CA-7	SAND	CONCRETE	OTHER
WASTE	(LOADS)	(TONS)	SEED	(TONS)	(TONS)	(TONS)		
81.67	7	23.97	300	41.45	42.3			

Sampling Analysis Project #19321

A PPM 0 - 3" Front and Back A PPM PPM No. Street/Number Address

6" Front and Back

ack	В	PPM	No.	
3 - 6 Front and back	В	Mdd	No.	
3-5	В	Mdd	No.	

S No.

307

548

269

607

275

516

1415 lowa

Depth Excav. (inch)

12

			
()			
\sim			
$\overline{}$			
$\overline{}$			
			·
<u>)</u>			
)			
<u>)</u>			
)			
<u>)</u>			

1417 Iowa

Action Date: 02-24-97 Loadout: 02-25-97

Restoration Begins: 02-25-97 Restoration Completed: 03-03-97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 12 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 46.45 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:
 - *TL-26
 - *17-KW
 - *X331
- *Subcontractors:
 - *WMI

-landfill

*Petago

-sod

EASEMENT INFORMATION

This easement was completed after the Temporary Restraining Order (TRO) was lifted.

QUANTITY SUMMARY FOR

1417 lowa

SPE	ECIAL	BACKFILL	TOPSOIL	SOD OR	CA-6	CA-7	SAND	CONCRETE	OTHER
W	ASTE	(LOADS)	(TONS)	SEED	(TONS)	(TONS)	(TONS)		
[46.45	2	32.99	105	44.12	26.19		i i	

0 - 3" Front and Back A PPM A PPM Street/Number Address

A PPM Š. 236 1860

B B W 3 - 6" Front and Back B PPM o B M Š

o PPM No. 6 - 12" Front and Back
C C C
PPM PPM PPP
No. No. No.

Depth Excav. (inch)

871


12

947

565

1710

1417 lowa



X = SAMPLE POINT

1417 IOWA

TOTAL DEMINSIONS

122'X22'



Drawn By: JG	Checked By:
Date: 5/30/97	Approved By:
Scale: NTS	Drawing No:

	-			
$\overline{}$				
X 2				
\sim			·	
$\overline{}$				

1423 Iowa

Action Date: 03-04-97 Loadout: 03-06-97

Restoration Begins: 03-07-97 Restoration Completed: 03-08-97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 12 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 41.19 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:
 - *TL-26

*TCM 806

- *17-KW
- *X331
- *Subcontractors:
 - *WMI

-landfill

*Petago

-sod

EASEMENT INFORMATION

This easement was completed after the Temporary Restraining Order (TRO) was lifted.

QUANTITY SUMMARY FOR

1423 lowa

_	SPECIAL	BACKFILL	TOPSOIL	SOD OR	CA-6	CA-7	SAND	CONCRETE	OTHER
	WASTE	(LOADS)	(TONS)	SEED	(TONS)	(TONS)	(TONS)		
_	41.19	3	12.75	135	43.18	14.83			

	0 - 3	0 - 3" Front and Back	3ack
	۷	A	A
Street/Number	PPM	PPM	PPM
Address	No.	No.	No.

	€	•	
Street/Number	PPM	Wdd	4
Address	No.	No.	
423 lowa	824	687	

3ack	8	Wdd	- 11
6" Front and Back	В	PPM	-14
3 - 6"	В	PPM	-17

8	Wdd	No.
 В	PPM	No.
8	PPM	No.

ပ	Mdd	No.
၁	Wdd	No.
င	PPM	No.
	၁	C C C

בומות שומות	၁	PPM	No.	
7 - (M	٥.	


Depth Excav. (inch)

12

751
398

824

816



X = SAMPLE POINT

1423 IOWA

TOTAL DEMINSIONS

122'X24'



Drawn By: JG	Checked By:
Date: 5/30/97	Approved By:
Scale: NTS	Drawing No:

<u>-</u>		
\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \		

825 Madison

Action Date: 01-06-97 Loadout: 01-06-97

Restoration Begins: 01-07-97 Restoration Completed: 01-07-97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 6 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 19.03 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:
 - *TL-26
 - *17-KW
 - *X331
- *Subcontractors:
 - *WMI
 - -landfill
 - *Brockmeier Sod Farm
 - -sod

QUANTITY SUMMARY FOR

825 Madison

SPECIAL	BACKFILL	TOPSOIL	SOD OR	CA-6	CA-7	SAND	CONCRETE	OTHER
WASTE	(LOADS)	(TONS)	SEED	(TONS)	(TONS)	(TONS)		
19.03	2	11.72	180		Í			,

Sampling Analysis Project #19321

3ack	A	Mdd	No.
0 - 3" Front and Back	٧	Mdd	No.
0 - 3"	٧	Wdd	No.
		Street/Number	Address

8	PPM	No.	590 349
4	PPM	No.	683 140
A	PPM	No.	738 1490
A	PPM	No.	494 196
	Street/Number	Address	825 Madison

6 - 12" Front and	S	ЫЬМ	No.		153	
6 - 12"	ပ	PPM	No.		291	273
sack	В	PPM	No.	1	809	201
" Front and Back	8	MPM MPM	No. No.		167 608	744 201

'			
ack	ပ	PPM	No.
12" Front and Back	2	Mdd	No.
6 - 12"	၁	PPM	No.

Depth Excav. (inch)

9

177

1230 Madison

Action Date: 11-19-96 Loadout: 11-20-96

Restoration Begins: 11-21-96 Restoration Completed: 11-22-96

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 6 inches was established by USACE prior to work commencing.
- *The excavation of special waste yield a total of 44.49 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

* Kubota

*17-KW

* TCM-806

*X331

- *Subcontractors:
 - *WMI

-landfill

*Prochnow

-sod

QUANTITY SUMMARY FOR

1230 Madison

SPECIAL BACKFILL	TOPSOIL	SOD OR	CA-6	CA-7	SAND	CONCRETE OTHER	-
WASTE (LOADS)	(TONS)	SEED	(TONS)	(TONS)	(TONS)		_
44.49	71.99	300				,	

0 - 3" Front

% N	No.	No.	Address
ldd	PPM	PPM	Street/Number
A	V	٧	
ממני	U - 3 FIUIT AND DACK	ر د -	

696 727

1230 Madison

Back 3 - 6" Front and Back		Mdd Mdd Mdd	No. No. No. No.	573 573 765 1430
ront and Back	4	PPM P	No.	1080

,			
3ack	ပ	PPM	No.
12" Front and Back	၁	Mdd	No.
6 - 12"	၁	PPM	No.
			-


3ack	2	Wdd	No.
12" Front and Back	၁	Wdd	No.
6 - 12"	ပ	PPM	No.

Depth Excav. (inch)

ၑ

ပ	PPM	No.	313 1140
ပ	PPM	No.	279 622

31	17
279	622



-		
X ,		
\sim		
\smile		
\smile		
\smile		
		•

1603 Maple

Action Date: 02-03-97 Loadout: 02-07-97

Restoration Begins: 02-07-97 Restoration Completed: 02-11-97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 6 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 70.86 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:
 - *TL-26
 - *17-KW
 - *X331
- *Subcontractors:
 - *WMI

-landfill

*Petago

-sod

EASEMENT INFORMATION

This easement was completed after the Temporary Restraining Order (TRO) was lifted.

QUANTITY SUMMARY FOR

1603 Maple

SPECIAL	BACKFILL	TOPSOIL	SOD OR	CA-6	CA-7	SAND	CONCRETE	OTHER
WASTE	(LOADS)	(TONS)	SEED	(TONS)	(TONS)	(TONS)		
70.86	5	82.92	600	26.44				

0 - 3" Front and Back A PPM PPM No. Street/Number Address

A PPM Š 710 180

1603 Maple

3 - 6" Front and Back

PPM No. PPM No. PPM No.

14300

264


No. 6 - 12" Front and Back
C C C
PPM PPM PP
No. No. No


Depth Excav. (inch)

496

176

9





-				
-				
Secretary Control of the Control of				
$\overline{}$				
			·	
			·	

1607 Maple

Action Date: 01-04-97 Loadout: 01-07-97

Restoration Begins: 01-07-97 Restoration Completed: 01-08-97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 3 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 76.57 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:
 - *TL-26
 - *17-KW
 - *X331
- *Subcontractors:
 - *WMI

-landfill

*Petago

-sod

EASEMENT INFORMATION

This easement was completed after the Temporary Restraining Order (TRO) was lifted.

QUANTITY SUMMARY FOR

1607 Maple

SPECIAL	BACKFILL	TOPSOIL	SOD OR	CA-6	CA-7	SAND	CONCRETE	OTHER
WASTE	(LOADS)	(TONS)	SEED	(TONS)	(TONS)	(TONS)		
76.57	,	151.3	540		14.2			

0 - 3" Front and Back Street/Number Address

PPM No. A PPM PPM No.

3 - 6" Front and Back

B B Wo. B PP S B PPM

Ω BPM S 6 - 12" Front and Back Ne PPM No.

307 88

Depth Excav. (inch)

က


436

342

578

460

1607 Maple



1607 MAPLE TOTAL DEMINSIONS 90'X56'



Drawn By: JG	Checked By:
Date: 5/30/97	Approved By:
Scale: NTS	Drawing No:

	-		
()			
\sim			
$\overline{}$			•
$\overline{}$			•
			•
			•
			•

1610 Maple

Action Date: 02-13-97 Loadout: 02-14-97

Restoration Begins: 02-14-97 Restoration Completed: 02-17-97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 6 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 70.07 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:
 - *TL-26
 - *17-KW
 - *X331
- *Subcontractors:
 - *WMI

-landfill

EASEMENT INFORMATION

This easement was completed after the Temporary Restraining Order (TRO) was lifted.

QUANTITY SUMMARY FOR

1610 Maple

SPECIAL	BACKFILL	TOPSOIL	SOD OR	CA-6	CA-7	SAND	CONCRETE	OTHER
WASTE	(LOADS)	(TONS)	SEED	(TONS)	(TONS)	(TONS)		
70.07	4	103.59	495	15.58	17.03			

0 - 3" Front and Back PPM No. A PPM Street/Number Address

A M No.

3ack	8	PPM	No.	
6" Front and Back	В	PPM	No.	
3 - 6"	8	PPM	No.	

12" Front and Back C C PPM F	┙
	2
` 5 .	

Depth Excav. (inch)

9

203

122

644

350

413

542

1610 Maple

" married			
X 2			
		•	

Action Date: 02-19-97 Loadout: 02-24-97

Restoration Begins: 02-24-97 Restoration Completed: 03-03-97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 3 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 42.21 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:
 - *TL-26
 - *17-KW
 - *X331
- *Subcontractors:
 - *WMI

-landfill

EASEMENT INFORMATION

This easement was completed after the Temporary Restraining Order (TRO) was lifted.

QUANTITY SUMMARY FOR

SPECIAL	BACKFILL	TOPSOIL	SOD OR	CA-6	CA-7	SAND	CONCRETE	OTHER
WASTE	(LOADS)	(TONS)	SEED	(TONS)	(TONS)	(TONS)		
42.21		64.22	300	25.87	24.29			

Sampling Analysis Project #19321

0 - 3" Front and Back A PPM Street/Number Address

В РРМ PPM No. 951 700 Š PPM No. **528** 436

1614 Maple

6 - 12" Front and Back
C C C
PPM PPM PP
No. No. No. No.

PPM No.

PPM No.

Š

391

488

3 - 6" Front and Back

œ


197

No.

Depth Excav. (inch)

က

237



X = SAMPLE POINT

1614 MAPLE TOTAL DEMINSIONS 131'X48'



Drawn By: JG	Checked By:
Date: 5/30/97	Approved By:
Scale: NTS	Drawing No

--

1230 Madison

Action Date: 11-19-96 Loadout: 11-20-96

Restoration Begins: 11-21-96 Restoration Completed: 11-22-96

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 6 inches was established by USACE prior to work commencing.
- *The excavation of special waste yield a total of 44.49 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:
 - *TL-26

* Kubota

*17-KW

* TCM-806

- *X331
- *Subcontractors:
 - *WMI

-landfill

*Prochnow

-sod

QUANTITY SUMMARY FOR

1230 Madison

-	SPECIAL	BACKFILL	TOPSOIL	SOD OR	CA-6	CA-7	SAND	CONCRETE	OTHER
)	WASTE	(LOADS)	(TONS)	SEED	(TONS)	(TONS)	(TONS)		
	44.49		71.99	300		:			

Sampling Analysis Project #19321

	0 - 3"	0 - 3" Front and Back	ack
	4	۷	٧
Street/Number	Mdd	Mdd	Mdd
Address	No.	No.	No.

	⋖	∢	¥
Street/Number	PPM	PPM	Wdd
Address	No.	No.	No.
1230 Madison	969	1080	

3ack	В	PPM	No.
6" Front and Back	В	PPM	No.
3 - 6"	8	ььм	No.

Depth Excav. (inch)


1140

622

1430

765

	၁	PPM	No.	
	၁	PPM	No.	
•	ပ	PPM	No.	



		·
\smile		

Action Date: 01-08-97 Loadout: 01-23-97

Restoration Begins: 01-24-97 Restoration Completed: 02-17-97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 3 inches was established by USACE prior to work commencing.
- *The excavation of special waste yield a total of 108.18 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:
 - *TL-26
 - *17-KW
 - *X331
- *Subcontractors:
 - *WMI
 - -landfill
 - *Turf Mountain
 - -sod

EASEMENT INFORMATION

This easement was completed after the Temporary Restraining Order (TRO) was lifted.

QUANTITY SUMMARY FOR

SPECIAL	BACKFILL	TOPSOIL	SOD OR	CA-6	CA-7	SAND	CONCRETE	OTHER
WASTE	(LOADS)	(TONS)	SEED	(TONS)	(TONS)	(TONS)		
108.18		83.16	240	109.43	14.38			

Sampling Analysis Project #19321

	0 - 3"	0 - 3" Front and Back	3ack
	٧	٧	٧
Street/Number	Wdd	Wdd	dd
Address	No.	No.	ž

	3 - 6"	3 - 6" Front and Back	3ack
A	8	8	В
М	PPM	PPM	Wdd
No.	No.	No.	No.

8	PPM	No.	
8	PPM	No.	
8	PPM	No.	

C C PPM F No.	3ack	၁	Wdd	No.
₹\r T	Front and E	၁	Mdd	No.
PPM No.	6 - 12"	၁	PPM	No.

Depth Excav. (inch)

ന

276


241

250

414

452

587



X = SAMPLE POINT





Drawn By: JG	Checked By:
Date: 5/29/97	Approved By:
Scale: NTS	Drawing No:

•

Action Date: 03-03-97 Loadout: 03-04-97

Restoration Begins: 03-05-97 Restoration Completed: 03-05-97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 12 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 63.91 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:
 - *TL-26
 - *17-KW
 - *X331
- *Subcontractors:
 - *WMI

-landfill

EASEMENT INFORMATION

This easement was completed after the Temporary Restraining Order (TRO) was lifted.

QUANTITY SUMMARY FOR

,	SPECIAL	BACKFILL	TOPSOIL	SOD OR	CA-6	CA-7	SAND	CONCRETE	OTHER	
1	WASTE	(LOADS)	(TONS)	SEED	(TONS)	(TONS)	(TONS)			1
•	63.91	2	14.86	120	51.65	55.14				

Sampling Analysis Project #19321

	0 - 3	U - 3" Front and Back	Sack
	A	A	4
Street/Number	Wdd	PPM	PPM
Address	No.	No.	Ň

			_	
∢	Mdd	No.		
∢	PPM	No.	440	340
∢	PPM	No.	510	370
	Street/Number	Address	1628 Maple	

ack	Φ	PPM	No.
6" Front and Back	В	PPM	No.
3 - 6"	В	PPM	No.


	ပ	Wdd	Š.	200 920
7 . 0	ပ	Mdd	No.	530 98
	Ф	PPM	No.	.
ם היותות המלו	8	PPM	No.	750 780
>	В	Mdd	No.	160 320

lack	ပ	PPM	No.
12" Front and Back	ပ	PPM	No.
6 - 12"	ပ	PPM	No.

Sack C PPM No.	
6 - 12" Front and Back C	
C - 12 PPM No.	

Depth Excav. (inch)

12



X = SAMPLE POINT

1628 MAPLE TOTAL DEMINSIONS 120'X25'



Drawn By: Checked By:

Date: Approved By: 5/30/97 Scale: NTS Drawing No

< >			

Action Date: 12-31-96 Loadout: 01-02-97

Restoration Begins: 01-02-97 Restoration Completed: 01-03-97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 3 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 63.31 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:
 - *TL-26
 - *17-KW
 - *X331
- *Subcontractors:
 - *WMI

-landfill

*Turf Mountain

-sod

EASEMENT INFORMATION

This easement was completed after the Temporary Restraining Order (TRO) was lifted.

QUANTITY S	SUMMARY	FOR
------------	---------	-----

	SPECIAL	BACKFILL	TOPSOIL	SOD OR	CA-6	CA-7	SAND	CONCRETE	OTHER
	_WASTE	(LOADS)	(TONS)	SEED	(TONS)	(TONS)	(TONS)		
į	63.31		135.75	465	15.12				

Sampling Analysis Project #19321

0 - 3" Front and Back PPM No. Street/Number Address

A PPM A PPM

3 - 6" Front and Back œ

PPM No. PPM No. B B W ON

444

372

640

747

1633 Maple

6 - 12" Front and Back ပ


No. No. PPM Š

Depth Excav. (inch)

က

261

122



X = SAMPLE POINT





Drawn By: JG	Checked By:
Date: 5/29/97	Approved By:
Scale: NTS	Drawing No:

\smile		

Action Date: 12-10-96 Loadout: 12-13-96

Restoration Begins: 12-14-96 Restoration Completed: 12-16-96

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 3 inches was established by USACE prior to work commencing.
- *The excavation of special waste yield a total of 44.71 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:
 - *TL-26
 - *17-KW
 - *X331
- *Subcontractors:
 - *WMI

-landfill

*Brockmiere

-sod

EASEMENT INFORMATION

This easement was completed after the Temporary Restraining Order (TRO) was lifted.

QUANTITY SUMMARY FOR

SPECIAL	BACKFILL	TOPSOIL	SOD OR	CA-6	CA-7	SAND	CONCRETE	OTHER
WASTE	(LOADS)	(TONS)	SEED	(TONS)	(TONS)	(TONS)		
44.71		117.44	420	25.56	13.26		:	

Sampling Analysis Project #19321

A PPM 0 - 3" Front and Back PPM No. PPM No. Street/Number Address

593 721

1635 Maple

3 - 6" Front and Back

82	PPM	No.
8	Wdd	No.
8	PPM	No.

6 - 12" Front and Back

င	PPM	No.
ပ	Wdd	No.
ပ	PPM	No.

Depth Excav. (inch)

261

148

475

365

က

٠			

Action Date: 12-05-96 Loadout: 12-07-96

Restoration Begins: 12-07-96 Restoration Completed: 12-10-96

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 12 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 57.59 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:
 - *TL-26
 - *17-KW
 - *X331
- *Subcontractors:
 - *WMI
 - -landfill
 - *Prochnow Landscaping -sod

EASEMENT INFORMATION

This easement was completed after the Temporary Restraining Order (TRO) was lifted.

QUANTITY SUMMARY FOR

1637 Maple

SPECIAL	BACKFILL	TOPSOIL	SOD OR	CA-6	CA-7	SAND	CONCRETE	OTHER
WASTE	(LOADS)	(TONS)	SEED	(TONS)	(TONS)	(TONS)		
57.59	5	66.35	320	28.58				

!	0 - 3	0 - 3" Front and Back	3ack
	٧	٧	٧
Street/Number	Wdd	Wdd	dd
Address	No.	No.	Ň


	€	₹	₹
Street/Number	Wdd	Wdd	Wdd
Address	No.	No.	No.
637 Maple	420	435	!

3ack	8	Mdd	No.
6" Front and Back	8	Mdd	No.
3 - 6"	8	PPM	No.

3ack	ပ	Mdd	No.
12" Front and Back	၁	PPM	No.
6 - 12"	၁	PPM	No.

sack	ပ	Mdd	No.	
12" Front and Back	၁	PPM	No.	
6 - 12"	၁	PPM	No.	

Depth Excav. (inch)



X = SAMPLE POINT



TOTAL DEMINSIONS 123'X61'

OHM Corporation Findley, Ohio

Drawn By:
JG Checked By:
Date: Approved By:

Scale: NTS Drawing No:

1643 Maple

Action Date: 12-02-96 Loadout: 12-03-96

Restoration Begins: 12-03-96 Restoration Completed: 12-04-96

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 3 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 23.08 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:
 - *TL-26
 - *17-KW
 - *X331
- *Subcontractors:
 - *WMI

-landfill

*Prochnow Landscaping

-sod

EASEMENT INFORMATION

This easement was completed after the Temporary Restraining Order (TRO) was lifted.

QUANTITY SUMMARY FOR

1643 Maple

SPECIAL BACKFILL	TOPSOIL	SOD OR	CA-6	CA-7	SAND	CONCRETE	OTHER
WASTE (LOADS)	(TONS)	SEED	(TONS)	(TONS)	(TONS)	:	
23.08	55.22	240		28.34			

0 - 3" Front and Back A PPM Street/Number Address

A PPM No. PPM No. 231 909

3 - 6" Front and Back

8	PPM	No.
8	PPM	No.
В	ЬРМ	No.

Back	
and	
Front	
- 12"	
9	

	ပ	PPM	No.	
	၁	Mdd	No.	
1	၁	Mdd	No.	

Depth Excav. (inch)

က

92 183

320

326

1643 Maple

		·

1651 Maple

Action Date: 11-21-96 Loadout: 11-22-96

Restoration Begins: 11-23-96 Restoration Completed: 11-23-96

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 3 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 36.06 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:
 - *TL-26
 - *17-KW
 - *X331
- *Subcontractors:
 - *WMI
 - -landfill
 - *Prochnow Landscaping
 - -sod

QUANTITY SUMMARY FOR

1651 Maple

SPECIAL	BACKFILL	TOPSOIL	SOD OR	CA-6	CA-7	SAND	CONCRETE	OTHER
WASTE	(LOADS)	(TONS)	SEED_	(TONS)	(TONS)	(TONS)		
36.06		23.83	180	29.33	11.59			

A PPM		No.	No.	Address
6	<u>a</u>	PPM	Wdd	Street/Number
0 - 3" Front and Back		A	A	
	3ack	Front and E	0 - 3"	

			200
	4	4	٧
Street/Number	PPM	Mdd	Mdd
Address	No.	No.	No.
1651 Maple	910	1200	

ack	8	Wdd	No.	
6" Front and Back	8	PPM	No.	
3 - 6"	8	Wdd	No.	

6 - 12" Front and Back C C C PPM PPM F No. No.	3ack	၁	PPM	No.
	Front and E	၁	Wdd	No.
	6 - 12"	၁	PPM	No.

Depth Excav. (inch)


က

360

410

190

260



910 Niedringhaus

Action Date: 02-24-97 Loadout: 02-25-97

Restoration Begins: 02-25-97 Restoration Completed: 02-25-97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 3 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 18.73 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:
 - *TL-26
 - *17-KW
 - *X331
- *Subcontractors:
 - *WMI

-landfill

EASEMENT INFORMATION

This easement was completed after the Temporary Restraining Order (TRO) was lifted.

QUANTITY SUMMARY FOR

SPECIAL	BACKFILL	TOPSOIL	SOD OR	CA-6	CA-7	SAND	CONCRETE	OTHER
WASTE	(LOADS)	(TONS)	SEED	(TONS)	(TONS)	(TONS)		
18.73	i		·		43.4		·	<u> </u>

A PPM 0 - 3" Front and Back A PPM PPM No. Street/Number Address

2 . G" Eron

sack	8	PPM	No.	
3 - 6 Front and Back	В	PPM	No.	
3-6	8	PPM	No.	

	_
3ack	
and E	
Ħ	١

8	PPM	No.	
8	PPM	No.	
8	PPM	No.	

	ı	
¥	ŀ	
ਹ	ı	
Back	۱	
$\mathbf{\omega}$	ŀ	
	ı	
and	ı	
	ı	
w	ı	
Ħ	۱	
ō	ı	
2	ı	
ŭ.	ı	
-	ļ	
הֿ	1	
-	Ì	
	I	
÷	l	
9	ı	
	١	

ပ	PPM	No.
ပ	PPM	No.
ပ	Mdd	No.

Depth Excav. (inch)

က

413


338

463

428

470

596



X = SAMPLE POINT

910 NIEDRINGHAUS

TOTAL DEMINSIONS

113'X21'

OHM Corporation
Finday, Ohio

Drawn By:	Checked By:
Date: 5/30/97	Approved By:
Scale: NTS	Drawing No:

910 1/2 Niedringhaus

Action Date: 02-15-97 Loadout: 02-18-97

Restoration Begins: 02-19-97 Restoration Completed: 02-19-97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 6 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 45.15 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:
 - *TL-26
 - *17-KW
 - *X331
- *Subcontractors:
 - *WMI

-landfill

EASEMENT INFORMATION

This easement was completed after the Temporary Restraining Order (TRO) was lifted.

QUANTITY SUMMARY FOR

910 1/2 Niedringhaus

S	PECIAL	BACKFILL	TOPSOIL	SOD OR	CA-6	CA-7	SAND	CONCRETE	OTHER
_\	WASTE	(LOADS)	(TONS)	SEED	(TONS)	(TONS)	(TONS)		
	45.15		49.22	120	13.64	28.83			

	0 - 3	- 3" Front and Back	3ack
	٧	٧	
Street/Number	Mdd	Wdd	Ь
Address	No.	No.	2

)		100
	4	٧	V
Street/Number	PPM	Wdd	PPM
Address	No.	No.	No.
910.5 Niedringhaus	482	513	

Back	8	
ront and	8	
3 - 6"	8	


8	PPM	No.
8	PPM	No.
В	PPM	No.

	C
3ack	L
and	
Front	
3 - 12"	
9	

ပ	PPM	No.
ပ	PPM	No.
ပ	PPM	No.

Depth Excav. (inch)

Back	၁	dd	No
Front and	၁	Wdd	No.
- 12"		V	



910 1/2 NIEDRINGHAUS TOTAL DEMINSIONS

120'X21'

OHM Corporation
Findley, Ohio

Drawn By: JG	Checked By:
Date: 5/30/97	Approved By:
Scale: NTS	Drawing No:

912 Niedringhaus

Action Date: 03-03-97 Loadout: 03-03-97

Restoration Begins: 03-04-97 Restoration Completed: 03-06-97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 12 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 16.14 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:
 - *TL-26
 - *17-KW
 - *X331
- *Subcontractors:
 - *WMI

-landfill

EASEMENT INFORMATION

This easement was completed after the Temporary Restraining Order (TRO) was lifted.

QUANTITY SUMMARY FOR

	BACKFILL (LOADS)	 SOD OR SEED	CA-6 (TONS)	CA-7 (TONS)	SAND (TONS)	CONCRETE	OTHER	11111
16.1	4	 STONE	42.06	29.12	···			

0 - 3" Front and Back A M No. Street/Number Address

A PPM No. 1200 PPM No. 1200

6" Front and Back	8	Wdd	NO
	8	Wdd	ON
3 - 6"	8	Mdd	S

	В	PPM	No.	
	8	Wdd	No.	
)	8	Mdd	No.	

	_		\Box
sack	ပ	Mdd	No.
12" Front and Back	၁	PPM	No.
6 - 12"	ပ	Mdd	No.

Depth Excav. (inch)

12


၁	Wdd	No.	
ပ	PPM	No.	

520

2300

1300

1500



\sim \sim			
			•
\smile			

929 Niedringhaus

Action Date: 11-12-96 Loadout: 11-21-96

Restoration Begins: 11-21-96 Restoration Completed: 11-27-96

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 6 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 155.23 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:
 - *TL-26
 - *17-KW
 - *X331
- *Subcontractors:
 - *WMI

-landfill

*Prochnow Landscaping

-sod

QUANTITY SUMMARY FOR

SPECIAL	BACKFILL	TOPSOIL	SOD OR	CA-6	CA-7	SAND	CONCRETE	OTHER	-
WASTE	(LOADS)	(TONS)	SEED	(TONS)	(TONS)	(TONS)		_	_:
155.23		12.05	60	275.24	138.42				7

A PPM 0 - 3" Front and Back A PPM A PPM è Sampling Analysis Project #19321 Street/Number Address

3 - 6" Front and Back B B B PPM No. No.				П
3 - 6" Front and E B B BPM PPM No. No.	sack	8	PPM	No.
3 - 6 B PPM No.	Front and E	8	Wdd	No.
	3-6	B	PPM	No.

Back	၁	PPM	No.
12" Front and B	၁	PPM	No.
6 - 12"	၁	PPM	No.

Depth Excav. (inch)

9

8	PPM	No.
60	Mdd	No.
8	PPM	No.

Mdd	No.	
PPM	No.	

436

804

971

\sim			
\ .			
\sim			

931 Niedringhaus

Action Date: 11-12-96 Loadout: 11-18-96

Restoration Begins: 11-22-96 Restoration Completed: 11-23-96

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 12 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 112.65 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:
 - *TL-26

*TCM 806

- *17-KW
- *X331
- *Subcontractors:
 - *WMI

-landfill

*Prochnow

-sod

QUANTITY SUMMARY FOR

931 Niedringhaus

SPECIAL	BACKFILL	TOPSOIL	SOD OR	CA-6	CA-7	SAND	CONCRETE	OTHER
WASTE	(LOADS)	(TONS)	SEED	(TONS)	(TONS)	(TONS)		
112.65	5	11.49	60	84.75	24.58			·

PPM No. 0 - 3" Front and Back A PPM o PPM No. Street/Number Address

3 - 6" Front and Back

	8	Wdd	No.
	8	Mdd	No.
)	8	PPM	No.

481

616

931 Niedringhaus

Back	ပ	
Front and	၁	
6 - 12"	၁	

3ack	ပ	PPM	No.
12" Front and Back	ပ	PPM	No.
6 - 12"	၁	Wdd	No.

Depth Excav. (inch)

12

519

\smile			
,			
$\overline{}$			
$\overline{}$			

935 Niedringhaus

Action Date: 11-12-96 Loadout: 11-15-96

Restoration Begins: 11-15-96 Restoration Completed: 11-27-96

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 12 inches was established by USACE prior to work commencing.
- *The excavation of special waste yield a total of 151.37 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

*TCM 806

*17-KW

*X331

- *Subcontractors:
 - *WMI

-landfill

*Prochnow Landscaping

-sod

QUANTITY SUMMARY FOR

935 Niedringhaus

SPECIAL	BACKFILL	TOPSOIL	SOD OR	CA-6	CA-7	SAND	CONCRETE	OTHER
WASTE	(LOADS)	(TONS)	SEED	(TONS)	(TONS)	(TONS)		
151.37		30.67	60	201.19	86.09		1	

0 - 3" Front and Back PPM No. PPM No. **Street/Number** Address

Back	8	
ront and	8	
3-6"	В	

Cach	8	PPM	No.
ו טוו מווע סמטו	8	PPM	No.
) 	8	Wdd	No.

A PPM

6 - 12" F	ပ	PPM	No.
sack	8	PPM	No.
Front and Back	8	Mdd	No.

lack	ပ	PPM	No.
12" Front and Back	၁	PPM	No.
6 - 12"	၁	Mdd	No.

3ack	၁	Mdd	No.
12" Front and Back	၁	PPM	No.
6 - 12"	၁	Mdd	No.

Depth Excav. (inch)

12

၁	PPM	No.	574
င	PPM	No.	305

520

150


902 610

342 450


821 510

480 **2000**

935 Niedringhaus



935 NIEDRINGHAUS



1632 Olive

Action Date: 02-03-97 Loadout: 02-08-97

Restoration Begins: 02-08-97 Restoration Completed: 02-15-97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 12 inches was established by USACE prior to work commencing.
- *The excavation of special waste yield a total of 107.97 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:
 - *TL-26
 - *17-KW
 - *X331
- *Subcontractors:
 - *WMI

-landfill

EASEMENT INFORMATION

This easement was completed after the Temporary Restraining Order (TRO) was lifted.

QUANTITY SUMMARY FOR

1632 Olive

SPECIAL	BACKFILL	TOPSOIL	SOD OR	CA-6	CA-7	SAND	CONCRETE	OTHER
WASTE	(LOADS)	(TONS)	SEED	(TONS)	(TONS)	(TONS)		
107.97	8	113.05	360					·

0 - 3" Front and Back A PPM % Street/Number Address

A PP O A PPM 140 340

3 - 6" Front and Back ∞ PPM No.

PPM No. No.

No. 6 - 12" Front and Back PPM No. No.

Depth Excav. (inch)

12


2000 436


430 352

440

150

1632 Olive







1636 Olive

Action Date: 02-08-97 Loadout: 02-13-97

Restoration Begins: 02-14-97 Restoration Completed: 02-15-97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 6 inches was established by USACE prior to work commencing.
- *The excavation of special waste yield a total of 31.29 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:
 - *TL-26
 - *17-KW
 - *X331
- *Subcontractors:
 - *WMI

-landfill

*Turf Mountain

-sod

EASEMENT INFORMATION

This easement was completed after the Temporary Restraining Order (TRO) was lifted.

QUANTITY SUMMARY FOR

1636 Olive

SPECIAL B	ACKFILL	TOPSOIL	SOD OR	CA-6	CA-7	SAND	CONCRETE	OTHER
WASTE (LOADS)	(TONS)	SEED	(TONS)	(TONS)	(TONS)		
31.29		7.93	120		45.48			

0 - 3" Front and Back PPM No. Street/Number Address

PPM No. PPM No.

3 - 6" Front and Back 8

B PPM PPM ş B PPM oN

6 - 12" Front and Back

o PP oS PPM No. PPM ģ ပ

346

229

1100

361


474

678

1636 Olive

Depth Excav. (inch)

9



1638 Olive

Action Date: 02-08-97 Loadout: 02-13-97

Restoration Begins: 02-14-97 Restoration Completed: 02-15-97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 6 inches was established by USACE prior to work commencing.
- *The excavation of special waste yield a total of 39.09 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:
 - *TL-26
- *Kubota
- *17-KW
- *X331
- *Subcontractors:
 - *WMI

-landfill

*Turf Mountain

-sod

EASEMENT INFORMATION

This easement was completed after the Temporary Restraining Order (TRO) was lifted.

QUANTITY SUMMARY FOR

1638 Olive

-			TOPSOIL		CA-6	CA-7		CONCRETE	OTHER
	WASTE	(LOADS)	(TONS)	SEED	(TONS)	(TONS)	(TONS)		
	39.09		21.26	60	28.78	14.91			·

0 - 3" Front and Back

ımber PPM PPM PPM ISS No. No.		٧	٧	۷
No. No.	ımber	Mdd	Wdd	PPM
	SS	No.	No.	No.

Back	8
Front and	8
3 - 6"	В

8	PPM	No.
В	PPM	No.
8	Mdd	No.

Back	
t and	
Front	
12"	
9	

၁	PPM	No.
၁	Wdd	No.
၁	Mdd	No.

332

Street/Nun


1638 Olive

756

575

Depth Excav. (inch)

9



X = SAMPLE POINT

TOTAL DEMINSIONS

125'X41'

онм 🞾 Corporation
Findley, Ohio

Drawn By:	Checked	Ву:
Date: 5/29/97	Approve	d By:
Scale: N	TS Drawing	No:

		·

1618 Spruce

Action Date: 01-24-97 Loadout: 01-31-97

Restoration Begins: 02-01-97 Restoration Completed: 02-03-97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 3 inches was established by USACE prior to work commencing.
- *The excavation of special waste yield a total of 128.13 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:
 - *TL-26
- *TCM 806
- *17-KW
- *X331
- *Subcontractors:
 - *WMI

-landfill

EASEMENT INFORMATION

This easement was completed after the Temporary Restraining Order (TRO) was lifted.

QUANTITY SUMMARY FOR

1618 Spruce

SPECIAL	BACKFILL	TOPSOIL	SOD OR	CA-6	CA-7	SAND	CONCRETE OTHER
WASTE	(LOADS)	(TONS)	SEED	(TONS)	(TONS)	(TONS)	
128.13	5	122.15	587	84.79	16.18		

A		•		200
		A	Α	ď
Street/Number PPM PPM	Street/Number	PPM	PPM	dd
Address No. No.	Address	No.	No.	Ž

	3 - 6"	3 - 6" Front and Back	3ack
A	В	8	_
PM	PPM	Wdd	Ы
۱o.	No.	No.	Ž

Back	3	Wdd	No.
12" Front and E	၁	PPM	No.
6 - 12"	၁	PPM	No.
		W	

Depth Excav. (inch)

က

10

173

36

403

75

1690

1618 Spruce

,		
\sim		
	·	
\sim		
_		
·		

1646 Spruce

Action Date: 11-13-96 Loadout: 11-16-96

Restoration Begins: 11-16-96 Restoration Completed: 11-21-96

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 6 inches was established by USACE prior to work commencing.
- *The excavation of special waste yield a total of 107.43 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:
 - *TL-26
 - *17-KW
 - *X331
- *Subcontractors:
 - *WMI
 - -landfill
 - *Prochnow Landscaping
 - -sod

QUANTITY SUMMARY FOR

1646 Spruce

SPECIAL			SOD OR	CA-6	CA-7 (TONS)		CONCRETE	OTHER
107.43	(LOADS)	63.36	SEED 300		69.49	(TONS)		

0 - 3" Front and Back A PPM No. Street/Number Address

A PPM A PPM

B B S 3 - 6" Front and Back PPM No. m PPM No.

6 - 12" Front and Back No. PPM Š

398

1646 Spruce

746

234


771

98

PPM No.

Depth Excav. (inch)

9



1646 SPRUCE

TOTAL DEMINSIONS

128'X42'



Drawn E	By: JG	Checked By:
Date: 5/29/9	7	Approved By:
Scale:	NTS	Drawing No:

			•
No. of the second secon			
•			
			

1318/20 State

Action Date: 03-03-97 Loadout: 03-04-97

Restoration Begins: 03-05-97 Restoration Completed: 03-05-97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 6 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 61.12 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:
 - *TL-26
 - *17-KW
 - *X331
- *Subcontractors:
 - *WMI

-landfill

QUANTITY SUMMARY FOR

1318/20 State

SPECIAL	BACKF	ILL	TOPSOIL	SOD OR	CA-6	CA-7	SAND	CONCRETE	OTHER
WASTE	∣(LOAD	S)	(TONS)	SEED	(TONS)	(TONS)	(TONS)		
61.12	2	5	47.91	300	14.55	58.68		<u> </u>	

0 - 3" Front and Back Street/Number Address

PPM No. A PPM A MO.

3 - 6" Front and Back

8	PPM	No.
В	₽₽M	No.
В	Mdd	No.

	Į
Back	
and	
Front	ĺ
12"	1
9	I
	١

	၁	Wdd	No.
	ပ	PPM	No.
)	ပ	PPM	No.

Depth Excav. (inch)

9

307

731

979

1318/20 State

	 			
	-		-	
< /				
\sim				
\smile				

1344 State

Action Date: 12-02-96 Loadout: 12-05-96

Restoration Begins: 12-05-96 Restoration Completed: 12-07-96

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 12 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 145.48 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:
 - *TL-26
 - *17-KW
 - *X331
- *Subcontractors:
 - *WMI

-landfill

*Prochnow Landscaping

-sod

EASEMENT INFORMATION

This easement was completed after the Temporary Restraining Order (TRO) was lifted.

QUANTITY SUMMARY FOR

1344 State

SPECIAL	BACKFILL	TOPSOIL	SOD OR	CA-6	CA-7	SAND	CONCRETE	OTHER
WASTE	(LOADS)	(TONS)	SEED	(TONS)	(TONS)	(TONS)		
145.48	6	99.83	360	54.04	42.5			

0 - 3" Front and Back Street/

	۷	٧	4
Street/Number	PPM	Mdd	PPM
Address	No.	No.	No.
1344 State	1360	485	

3ack	8	Mdd	No.	
6" Front and Back	8	PPM	No.	
3 - 6"	8	Mdd	No.	


ပ	PPM	No.	1150 874
8	РРМ	No.	
œ	PPM	No.	587 1030
8	Mdd	No.	1030 591

			_
ack	၁	PPM	No.
12" Front and Back	၁	PPM	No.
6 - 12"	၁	PPM	No.

Depth Excav. (inch)

12

240 **734**



1720 State

Action Date: 11-18-96 Loadout: 11-19-96

Restoration Begins: 11-21-96 Restoration Completed: 12-02-96

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 6 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 58.05 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:
 - *TL-26
 - *17-KW
 - *X331
- *Subcontractors:
 - *WMI

-landfill

*Prochnow Landscaping

-sod

EASEMENT INFORMATION

This easement was completed after the Temporary Restraining Order (TRO) was lifted.

QUANTITY SUMMARY FOR

1720 State

	SPECIAL	BACKFILL	TOPSOIL	SOD OR	CA-6	CA-7	SAND	CONCRETE	OTHER	٠
1	WASTE	(LOADS)	(TONS)	SEED	(TONS)	(TONS)	(TONS)			
	58.05	·	69.16	360	27.2					_

0 - 3" Front and Back PPM No. PPM No. Street/Number Address

A PPM

B B W 3 - 6" Front and Back PPM No. œ B PPM 98

PPM No. 6 - 12" Front and Back PPM

PPM Š. Š

Depth Excav. (inch)

ဖ

300

390


630

810

900

970

1720 State



X = SAMPLE POINT

1720 STATE

TOTAL DEMINSIONS

110'X44'



Drawn By: JG	Checked By:
Date: 5/29/97	Approved By:
Scale: NTS	Drawing No:

	-	-
	-	
\sim		

1725 State

Action Date: 11-11-96 Loadout: 11-15-96

Restoration Begins: 11-15-96 Restoration Completed: 11-23-96

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 6 inches was established by USACE prior to work commencing.
- *The excavation of special waste yield a total of 164.39 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:
 - *TL-26
- *TCM 806
- *17-KW
- *X331
- *Subcontractors:
 - *WMI
 - -landfill
 - *Prochnow
 - -sod
 - *C. Grantham

QUANTITY S	SL	JMI	MΑ	RY	FOR
------------	----	-----	----	----	-----

1725 State

SPECIAL	BACKFILL	TOPSOIL	SOD OR	CA-6	CA-7	SAND	CONCRETE	OTHER
WASTE	(LOADS)	(TONS)	SEED	(TONS)	(TONS)	(TONS)		
164.39	10	343.17	900		13.32			

0 - 3" Front and Back PPM No. PPM No. Street/Number Address

A PPM 729 1330

1725 State

3 - 6" Front and Back

B PPM No. B PPM Š B PPM Š

6 - 12" Front and Back

o Ma S No. No.

445


244


640

730

9

Depth Excav. (inch)





-

1808/10 State

Action Date: 12-02-96 Loadout: 12-03-96

Restoration Begins: 12-03-96 Restoration Completed: 12-03-96

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 3 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 21.35 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:
 - *TL-26
 - *17-KW
 - *X331
- *Subcontractors:
 - *WMI

-landfill

QUANTITY SUMMARY FOR

1808/10 State

[SPECIAL	BACKFILL	TOPSOIL	SOD OR	CA-6	CA-7	SAND	CONCRETE	OTHER
	WASTE	(LOADS)	(TONS)	SEED	(TONS)	(TONS)	(TONS)		
	21.35				14.41	39.74			· · · · · · · · · · · · · · · · · · ·

0 - 3" Front and Back

	٧	4	4
mber	PPM	Mdd	PPM
SS	No.	No.	No.

×	۵
Back	L
and	
ront	0
19	ŀ
3-	L
	٩

sack	8	Wdd	No.	
 6" Front and Back 	В	PPM	No.	
3-6"	8	Mdd	No.	

~
\overline{c}
Bacl
**
ш
_
ъ
and
≂
w
-
$\overline{}$
٥
\sim
ш
-
2
N
~
٠
9
¥

ပ	Wdd	No.
ပ	PPM	No.
ပ	PPM	No.

Depth Excav. (inch)

243

302


	٧	۷	
Street/Number	PPM	Mdd	_
Address	No.	No.	

290

1808/10 State

PPM No.	A PPM
------------	-------

က



X = SAMPLE POINT





Drawn By: JG	Checked By:
Date: 5/30/97	Approved By:
Scale: NTS	Drawing No:

•		
\sim		
X 2		
\sim		

Action Date: 11-21-96 Loadout: 12-06-96

Restoration Begins: 12-06-96 Restoration Completed: 12-10-96

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 12 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 183.86 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

*TCM 806

*17-KW

*X331

- *Subcontractors:
 - *WMI

-landfill

*Brockmierer Sod Farm

-sod

EASEMENT INFORMATION

This easement was completed after the Temporary Restraining Order (TRO) was lifted.

QUANTITY SUMMARY FOR

2005 14th Street

SP	ECIAL	BACKFILL	TOPSOIL	SOD OR	CA-6	CA-7	SAND	CONCRETE	OTHER
W	ASTE_	(LOADS)	(TONS)	SEED	(TONS)	(TONS)	(TONS)		
1	83.86	12	149.66	720	13.24	94.67		:	

Action Date: 11-21-96 Loadout: 12-03-96

Restoration Begins: 12-03-96 Restoration Completed: 12-04-96

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 12 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 201.55 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:
 - *TL-26
- *TCM 806
- *17-KW
- *X331
- *Subcontractors:
 - *WMI
 - -landfill
 - *Brockmierer Sod Farm
 - -sod

EASEMENT INFORMATION

This easement was completed after the Temporary Restraining Order (TRO) was lifted.

QUANTITY SUMMARY FOR

2007 14th Street

SPECIAL	BACKFILL	TOPSOIL	SOD OR	CA-6	CA-7	SAND	CONCRETE	OTHER	1 1 1
WASTE	(LOADS)	(TONS)	SEED	(TONS)	(TONS)	(TONS)			
201.55	15	177.53	900	25.17	26.4				

0 - 3" Front and Back PPM No. PPM No. Street/Number Address

A PPM 418 225 1030 1440 2005/07 14th


B M o 3 - 6" Front and Back œ PPM No.

No. 6 - 12" Front and Back

PPM No. 107 30 **780** No PPM **661** 98 180

12

Depth Excav. (inch)



X = SAMPLE POINT

2007 14TH ST.

TOTAL DEMINSIONS

129'X61'



Drawn E	By: JG	Checked By:
Date: 5/29/9)7	Approved By:
Scale:	NTS	Drawing No: